

Remington Arms Co., Inc.
Product Service
Legal Case #:3667

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
172621	8/6/2009	8/7/2009	8/7/2009				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Mt Man Tradin Post		Mt Man Tradin P	1741 S St Rt 53	Tiffin	OH	44883		W 419-448-4255

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	fires when closing bolt			
C	Concern:1008 Fired on Bolt Closing			

8/13/09 Note with rifle states the gun is firing when bolt closes.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	20000	6802516	PY	6/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAMMES GUNS BELEFONTAINE OHIO	TWO PIECE SCOPE BASE	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA under BLSMP price						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$60.00	8/13/2009				

8/13/09 Could not duplicate concern. Trig assm dirty, parts work sluggish. Replace TPA, check over, clean under bolt lock program for \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/7/2009
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4015	Improper Maintenance	

Barrel	Description		22" 270 WIN
	Date Code		PY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
Bolt	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
Extractor	Stop	Slightly Worn; Functioning	SLUGGISH
	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
Locking	Ext/Eject Test	False	
	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
Overall	Notch Condition	---Select---	
	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
Receiver	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	
Safety	Bulged	False	
	Description		STANDARD M/700 BOLT LOCK SAFETY
Scar	Function	Like new; Functioning	
	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	SLUGGISH
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY/SLUGGISH
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	

Horton Bow
Gold Dealer



Mountain Man Tradin Post, LLC

1741 S. St. Rt. 53 Tiffin, Ohio 44883
419-448-4255 OR 1-866-676-8601
Fax: 419-448-9197



Savage
Arms Dealer

22"
246/74
4#
1007

Hours: M, W, F 4-8 • T, Th 10-4:30 • Sat 9-5 • Sun 12-4

Blackpowder ~ Tanned Hides ~ Crafts ~ Knives ~ Guns ~ Cast Iron Ware ~ Candles ~ Beads
Leather ~ Archery ~ Fishing ~ Live Bait ~ Gunsmith ~ Garb ~ Honey ~ Camping Supplies

Date 8-3-09

Name _____

Company _____

Address _____

Phone _____

Quantity	Description	Price
	Gun is firing when	
	Bolt closes	
	could not duplicate concern.	
	Tilg. ASSM dirty, parts work	
	cluggish. Replace TPA, check out	
	clean under bolt Locil program	
	Rev \$20.00 + S+H Quote	

Serial
Number

6802516

Model: **700**



RE00172621

total

Tax

Total