

Remington Arms Co., Inc.
Product Service
Legal Case #:4080

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
182219	12/4/2009	12/7/2009	12/7/2009				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Stephen	Petty	7341 Greenwood Rd	Harrison	TN	37341		H 423-344-8720 E stephen_raminc@comcast.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015	Improper Maintenance		
S	fires on safe release	Concern:1007	Fired on Safe Release	Unknown
C				

12/9/09 Per note with rifle, when you move from safe to fire it fired.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM-08 REM	27453	E6751276	KV	5/24/2001 5:47:58 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTS SOUTH INC	TWO PIECE SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, check over, clean at 1/2 normal charges						
	Repair/Replacement Cost	Repair/Replacement Date				
	48.84	12/9/2009				

12/9/09 Per Supry, trigger, trigger pin rusted, trigger binding back. Replace TPA, check over, clean at 1/2 normal charges.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/7/2009
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4015	Improper Maintenance	
Barrel	Description		20" 7MM-08 REM
	Date Code		KV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG AND PIN RUSTED TRIG STICKS BACK
	Pull	---Select---	10+#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

2011
KV S/OI
10 + 12

(NOTE: Please print and complete this form, and then include it with your firearm.)

of rounds)	1	1	1	1
or Number of rounds)	1	1	1	1

RE00182219

TR19 + TR19. PIN RUSTED.
TR19. DIVIDING BACK. Replace
TPA, check over, clean AT
1/2 normal changes.
Quote