

Remington Arms Co., Inc.
Product Service
Legal Case #:5430

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
214352	12/13/2010	12/15/2010	12/15/2010				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Allison & Carey Gunworks	---	Allison & Carey	17311 SE Stark	Portland	OR	97233		W 503-256-5166

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

RARC sent gun in for consumer. Consumer told them that ML will fire when safety is taken off. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	ML/BA	700/54 CAL	27582	ML225932	KS	9/8/1998
Date Purchased	Where Purchased	Accessories	Original Owner			
	ALL SPORTS LLC	PEEP SIGHT	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/ML/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair						
	Repair/Replacement Cost	Repair/Replacement Date				

Per Ilion - TA rusted, trigger binding. Replace TA, clean & check over at 1/2 normal charges - quote. df 1/7/11: I called & left msg for RARC to call me about the quote. df *1/9 Approved by fax T. Beaulieu.*

Examination[Remington/ML/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/15/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		24" 54 CAL SS
	Date Code		KS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	RUSTY

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	ACTION RUSTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY TRIG BINDING
	Pull	---Select---	10#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		PEEP SIGHT

ALLISON CASE WORKS, INC.
17311 S.E. Stark
Portland, Oregon 97233
(503) 256-5166

5430


customer called
factory, they told
him to bring
the rifle to us,
to send to Rem.

Fines when
taken off safety

Serial
Number:

ML225932

Model: 700ML



RE00214352

24"

54 CAL

1055/91

10#

T.A. rusted, trig. binding.
replace TPA, clean + check.
AT 1/2 normal charges.

Quote

RECEIVED
DEC 22 2010

BY:.....

