Remington Arms Co., Inc. Product Service Legal Case #:4856

Case Information

RE# Date Opened(PS) **Date Closed Date Opened Incident Date** Pre Lit Obsolete 209639 11/8/2010 10/26/2010 11/9/2010

Customer Information

Business First Name Last Name Street Zip Age Type City State Contact C 763-234-1364 14211 Blackfoot St. NW Incident Cyril M. Larson Andover MN 55304 E skip.larson@comcast.net

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status** 

ΡĪ

PD Cause: 4038 Could Not Duplicate Concern

Unknown Concern: 1008 Fired on Bolt Closing

C FBC

10/26/10: Customer called in. He had FBC last fall while hunting. No injury-No damage. df

Firearm Information

Mfg. Model/Ga. SKU DOM Type Serial Bbl. 700/300 WIN MA 27482 7/24/2001 10:00:39 PM Remington CF/BA E6765740 OV

**Date Purchased** Where Purchased Original Owner Accessories

Bought used from a friend SLING N

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Date Cash Cash Settlement Release of Claims Release Date Reimbursement APV Date APV Settlement

Per Ilion - Replace TA, clean, test @ n/c

Repair/Replacement Cost Repair/Replacement Date

\$47.23

11/10/2010

10/26/10: Sending ARS, letter, & form. df 11/10/10: Per Fred S. - Could not duplicate concern. Check over, replace TA to restore confidence in rifle, clean & test @ n/c. df 11/11/10: I spoke w/cust. & went over report & repairing @ n/c. He was fine w/our resolution. df


Examination[Remington/CF/BA]

| Part        | Sub-Part               | Code                        | Comment         |
|-------------|------------------------|-----------------------------|-----------------|
| Examination | Examiner               |                             | B.TRAVIS        |
|             | Exam Date              |                             | 11/9/2010       |
|             | Product Type           |                             | RF              |
|             | Action Type            |                             | A               |
|             | Assigned To            |                             | F.SUPRY         |
| Cause       | 4038                   | Could Not Duplicate Concern |                 |
| Barrel      | Description            |                             | 24" 300 WIN MAG |
|             | Date Code              |                             | OV              |
|             | Bore Plugged           | False                       |                 |
|             | Bulged                 | False                       |                 |
|             | Fired                  | False                       |                 |
|             | Fired while Obstructed |                             |                 |
|             | Muzzle/Crown Condition | Slightly Worn; Functioning  |                 |


http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4856&Type=Case

11/11/2010


| Bolt         | Firing Pin         | Slightly Worn; Functioning |                       |
|--------------|--------------------|----------------------------|-----------------------|
|              | Shroud             | Slightly Worn; Functioning |                       |
|              | Face               | Slightly Worn; Functioning |                       |
|              | Handle             | Slightly Worn; Functioning |                       |
|              | Stop               | Slightly Worn; Functioning |                       |
|              | Condition          | Slightly Worn; Functioning |                       |
| Extractor    | Cut Condition      | Slightly Worn; Functioning |                       |
|              | Ext/Eject Test     | False                      |                       |
|              | Block Condition    | Select                     |                       |
| Locking      | Lug Condition      | Slightly Worn; Functioning |                       |
|              | Notch Condition    | Select                     |                       |
|              | Exterior Condition | Slightly Worn; Functioning |                       |
| Overall      | Stock Condition    | Slightly Worn; Functioning |                       |
|              | Fore End Condition | Select                     |                       |
| Receiver     | Condition          | Slightly Worn; Functioning |                       |
| Receiver     | Bulged             | False                      |                       |
|              | Description        |                            | STANDARD M/700 SAFETY |
| Safety       | Function           | Like new; Functioning      |                       |
|              | Sub-Assembly       | ISS                        |                       |
| Sear         | Lift               | Select                     | .016                  |
|              | Notch              | Like new; Functioning      |                       |
|              | Т4-                | Test Fired                 | False                 |
| Feeding Test | Tests              | False                      |                       |
| Trigger      | Condition          | Like new; Functioning      |                       |
|              | Pull               | Select                     | 7#                    |
|              | Altered            | False                      |                       |
|              | Sub-Assembly       | M/700 Non-Bolt Lock        |                       |



let customer know that caliber not available in BDL, we will install xmark pro under the bolt lock modification, TRED 11/9/10



4856



October 26, 2010

Cyril M. Larson 14211 Blackfoot St. NW Andover, MN 55304 Ph: 763-234-1364

Ref: #4856

Dear Mr. Larson,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the boxes with the name "Supry". Fred Supry will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,

D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

Fax: 336-548-7872

E6765740 Model: 700



could not duplicate concert. check own supmenTPA To sestore confidence in Rifle, clear + TUSTFINE AT H/C

# 230145

Remington Arms Company, Inc. ● 870 Remington Drive ● P.O. Box 700 ● Madison, NC 27025 Phone 800-243-9700 ● www.remington.com



| Factory Repair Form   |                                   | Return to Previous Pege | . 1   |
|---|-----------------------------------|-------------------------|-------|
| NOTE: Please complete and print this form, and then include i | t with your firearm.              |                         | DV,   |
| Model Number:   | Serial Number: 6                  | 765740                  | 116   |
| Are you the original owner?: YES X NO                         | C                                 | ,                       |       |
| Name HRIL MAX LA  | Cate of Furchase:                 | 0/1/10                  |       |
| Address (no PO Boxes): 14211 BL                               | ACKFOOT ST                        | NW                      |       |
| City: ANCALER   | State M N                         | Zip 55304-07            | 105   |
| Phone (Dayston) 13 - 234-136                                  | , (4x:                            |                         |       |
| E-mail Address:(if e-mail address is provided, notification   | n of receipt and shipment will be | 9                       |       |
| E-mail Address:   | OMICHSI, NE                       | •1                      |       |
| I would like to receive future e-mail updates from Re         | mington.                          |                         |       |
| Please describe your problem and date of occurrence           |                                   | A.                      |       |
| DURING RAPIL FIRE AS  | THE boilt C                       | المحادة                 |       |
| Riple Will Fire Also  |                                   | SAFETY.                 |       |
| Rear SwiveL is ba   | 1                                 |                         |       |
| ( day   | 8. 11/1/10                        | , wi                    |       |
| 500 characters left   | <u></u>                           | <u> </u>                |       |
| Ammunition Information:                                       |                                   | D                       |       |
| Manufacturer:   | Wybe:                             |                         | b_    |
| Other (i.e. bullet weight/type, shot size, powder):           | 17 Wo                             | ita it                  | DC-   |
|   | P                                 | SSILE                   | 70    |
| Handload Information: Powder Used:                            | Powder Weight:                    |                         | 70    |
| Case/Huli Used:   | Primer Used                       | DGRAGE                  | ₹ 70  |
| Bullet Type/Shot Size:  | Reloader Used:                    | ERDI                    | - 1   |
| dulet Typerotist O.E.   | 1.00000.000.                      |                         |       |
| Firearms Care (Cleaning and Lubrication):                     | VY                                | locel-Sm                | ne    |
| Brand of cleaning solution used:                              |                                   | Cal.                    | la co |
| How often do you clean the bore? (Months or Number of         | rounds)                           | THAN                    |       |
| How often do you clean the action? (Months or Number of       | frounds)                          | - Sn                    | M.    |
| How often do you clean the trigger assembly? (Months or       | Number of lounds)                 |                         | J-1   |
| Brand of lubricant used:                                      |                                   |                         |       |
| How often do you lubricate the bore? (Months or Number        | of rounds)                        |                         |       |
| How often do you lubricate the action? (Months or Numbe       | r of rounds)                      |                         |       |
|   |                                   |                         |       |

| How often do you lubricate the trigger assembly? (Month's or Number of rounds)   |
|--|
| Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES NO   |
| When was the last time that your firearm was selviced by a Reminaton authorized repairman/gunsmith?)   |
| What were the services performed?)   |
| Ship your INSURED firearm by either UPS or Parcel Post to:   |
| Remington Arms Co., Inc.<br>Attn: Arms Service Division<br>14 Hoefler Avenue<br>Ilion, NY 13357  |
| ① WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW, IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.   |
| Record the serial number of your firearm before sending it. Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) Remove all accessories from your firearm to prevent loss or damage. Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused. Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. |
| Charge repairs will be processed using the following guidelines:   |
| :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)  |
| :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.   |

© 2009 Remington Arms Company, Inc. All Rights Reserved. Investor Relations | Other Remington Brand Products | Legal Notices | About Us

Visit Our Other Websites
Other Sites .





Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

| DATE:                                     |                    | 10/26/2010 | REQUESTED BY:    | Dell      |
|---|--------------------|------------|------------------|-----------|
| QUANTITY:                                 |                    | 1          | WEIGHT PER PACKA | 4( 10 lbs |
| PLEASE CHECKONE MEDIA COORDINATOR TO MAIL |                    |            | I WILL MAIL      | xxxxx     |
| DESCRIPTION:                              | Ref# 4856<br>Rifle |            |                  |           |

## LABEL INFORMATION

MAIL LABEL TO: Cyril M. Larson

14211 Blackfoot St. NW Andover, MN 55304 Ph: 763-234-1364

RETURN ITEM TC Remington Arms

Attn: Product Service

Ilion, NY

## PLEASE COMPLETE ALL PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR