

Remington Arms Co., Inc.
Product Service
Legal Case #:4819

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
		10/21/2010					

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Timothy	Scott	500 S. Hassett PO Box 133	Tripp	SD	57376		C 605-505-0404

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI PD Shot hole in house S C	Cause:4079 Other - Unexamined Concern:1008 Fired on Bolt Closing		Unknown	

10/21/10: Customer called in. Saw CNBC show. About 1 1/2 yrs ago he was unloading his rifle inside the house & it fired when he closed the bolt & shot a hole in his house. No injury. He did not ask for any compensation. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	6687244		
Date Purchased	Where Purchased	Accessories	Original Owner			
	Given to him by a friend		N			

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Repair/Replacement Cost		Repair/Replacement Date				
10/21/10: Sending ARS, letter, form & box. Box order# 1151115. df						

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------



www.remington.com

Remington Arms Company, Inc.
870 Remington Drive
P. O. Box 700
Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	10/22/2010	REQUESTED BY:	Dell
QUANTITY:	1	WEIGHT PER PACKAGE:	10 lbs
PLEASE CHECK ONE			
MEDIA COORDINATOR TO MAIL		I WILL MAIL	xxxxxxx
DESCRIPTION: Ref# 4819 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Timothy Scott 500 S. Hassett PO Box 133 Tripp, SD 57376 Ph: 605-505-0404
RETURN ITEM TO Remington Arms Attn: Product Service Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 OCT 22, 2010 ALL CURR USD 1 OF 1
SVC GND COM ACT WT 10.0 LBS
TRACKING# 1Z4XX5963067726013
REF 1:TIMOTHY SCOTT/CD/DMF
REF 2:4819/RIFLE

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRG: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHG 9.49 PUB+HANDLING 9.49

Remington Arms Co., Inc.
Product Service
Legal Case #:5224

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
		11/29/2010		11/27/2010			

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Brett	Scroggins	12100 Fieldstone Ln. Apt B9	Bryant	AR	72022		H 501-681-2933

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4079	Other - Unexamined		
S	Concern:1007	Fired on Safe Release	Unknown	
C FSR				

11/29/10: Customer called in. He stated he was hunting on 11/27/10 & had a FSR. No damage, No injury. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 RUM	20000	S6695928		
Date Purchased	Where Purchased	Accessories	Original Owner			
			U			

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Repair/Replacement Cost		Repair/Replacement Date				

11/29/10: Sending ARS, ltr, form. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------