Remington Arms Co., Inc.
Product Service
Legal Case #:5041

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

214382 12/13/2010 11/9/2010 1/5/2011 10/8/2010

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Traident Northern Montove 4011 Rangeview Dr. Chevenne WV 82001

H 307-637-7253

Incident Nathan Montoya 4011 Rangeview Dr. Cheyenne WY 82001 E ibcrazynate@aol.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Shot a hole in friend's truck Cause:4038 Could Not Duplicate Concern

Concern:1008 Fired on Bolt Closing

Unknown

S C

Jeremy Padgett emailed in on behalf of Nathan Montoya. Jeremy & Nathan were hunting this past antelope season. Nathan got out of Jeremy's truck loaded his rifle & when he closed the bolt - the rifle fired. Shot a hole in Jeremy's truck. Damaged glove box, wire harnasses, firewall, & downpipe of exhaust. Jeremy wants us to pay for truck damage. df

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

Remington CF/BA 770/270 WIN 85632 71385092 OB 7/24/2007 4:18:15 PM

Date Purchased Where Purchased Accessories Original Owner

WAL-MART SUPERCENTER 1315 Y

CONCERN:FBC

Ammunition Information - None Defined
Other Products Information - None Defined
Settlement

Remington/770/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Settlement Release Date Reimbursement Release Date Settlement Release Date APV APV

Replace with ramac 27361 in exchange

Repair/Replacement
Cost
S193.57

Repair/Replacement
Date
1/5/2011

11/9/10: Sending ARS, ltr, form. df 12/30/10: Per Ilion - Could not duplicate concern. df 12/30/10 @ 10:33am ET - I called cust. No answer, No voice mail. I emailed him & asked him to call. I am willing to exchange for ramac 27361 - M/700 SPS, 270 Win. Must ship to a dealer also. df 1/5/11: Customer called. We agreed to ramac 27361 as replacement in exchange. Shipping to Marv's Other Place Pawn. Ashley @ store apprvd shipment. We have FFL on file. His friend Jeremy is supposed to fax over estimate for repairing truck. When he does, I will review & go from there. Release will need to be signed by Jeremy. df

Examination[Remington/CF/BA]


Part	Sub-Part	Code	Comment

1	Examiner		B.TRAVIS
Examination	Exam Date	=	12/15/2010
	Product Type	_	RF
	Action Type	=	A
	Assigned To	=	T.NAGLE
Cause	4038	Could Not Duplicate Concern	THACE
Cause	Description	·	22" 270 WIN
	Date Code	=	OB
	Bore Plugged	False	
Barrel	Bulged	False	
Barrel	Fired	False	
		raise	
	Fired while Obstructed	Cli tala Wassa Faradisaisa	
	Muzzle/Crown Condition	Slightly Worn; Functioning	_
	Firing Pin	Slightly Worn; Functioning	_
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Magazine	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/770 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	,
Sear	Notch	Like new; Functioning	7
		Test Fired	False
Feeding Test	Tests	False	
recuing rest	Condition	Like new; Functioning	=
	Pull	IISelect	(14#
Trigger	Pull Altered	Select False	4#

Bureau of Alcohol, Tobacco, Firearms and Explosives

Federal Firearms License (18 U.S.C. Chapter 44)

In accordance with the provisions of Title I, Gun Control Act of 1968, and the regulations issued thereunder (27 CFR Part 478), you are licensed to engage in the business specified in this license, within the limitations of Chapter 44, Title 18, United States Code, and the regulations issued thereunder, natil the expiration date shown. See "WARNINGS" and "NOTICES" on reverse. ATF - Chief, FFLC License 5-83-021-02-2H-00871 Direct ATF Number 244 Needy Road Correspondence To Martinsburg, WV 25405-9431 August 1, 2012 Chief, Federal Frearms Libensing Center (FFLC) Expiration Name MARVS OTHER PLACE Premises Address (Changes? Notify the FFLC at least 30 days before the move.) 3543 E LINCOLN, WAY CHEYENNE, WY 82001-Type of License 02-PAWNBROKER IN FIREARMS OTHER THAN DESTRUCTIVE DEVICES Purchasing Certification Statement Mailing Address (Changes? Notify the FFLC of any changes.) The licensee named above shall use a copy of this license to assist a transferor of MARVS PLACE INC firearms to verify the identity and the licensed status of the licensee as provided by MARVS OTHER PLACE 27 CFR Part 478. The signature on each copy must be an original signature. A faxed, scanned or e-mailed copy of the license with a signature intended to be an 3543 E LINCOLN WAY original signature is acceptable. The signature must be that of the Federal Firearms CHEYENNE, WY 82001-Licensee (FFL) or a responsible person of the FFL. I certify that this is a true copy of a license issued to the licensee named above to engage in the business specified above under Type of Lice Licensee/Responsible Person Signature 78-03-0⁴ Printed Name ATF Form 8 (5310.11) Revised September 2008 Previous Edition is Obselete Federal Firearms License (FFL) Customer Service Information Federal Firearms Licensing Center (FFLC) Toll-free Telephone Number: (866) 662-2750 ATF Homepage: www.atf.gov Toll-free Fax Number: (866) 257-2749 FFL eZ Check: www.atfonline.gov/filezeheck 244 Needy Road Martineburg, WV 25405-9431 E-mail: NLC@arf.gov Change of Address (27 CFR 478.52). Licensees may during the term of their current license remove their business or activity to a new location at which they intend regularly to carry on such business or activity by filing an Application for an Amended Federal Firearms License, ATF Form 5300.38, in duplicate, not less than 30 days pripr to such removal with the Chief, Federal Firearms Licensing Center. The application must be executed under the penalties of perjury and penalties imposed by 18 U.S.C 924. The application shall be accompanied by the licensee's original license. The license will be valid for the creatinder of the term of the original license. (The Chief, FFLC, shall, if the applicant is not qualified, refer the application for amended license to the Director of Industry Operations for denial in accordance with § 478.71.) Right of Succession (27 CFR 478,56). (a) Certain persons other than the licensee may secure the right to extry on the same firearms or ammunition business at the same address shown on, and for the remainder of the term of, a current license. Such persons are: (1) The surviving spouse or child, or executor, administrator, or other legal representative of a deceased licensee, and (2) A receiver or trustee in bankruptey, or an assignee for benefit of creditors. (b) In order to secure the right provided by this section, the person or persons continuing the business shall furnish the license for that business for endorsement of such succession to the Chief, FFLC, within 30 days from the date on which the successor begins to carry on the business MARN'S OTHER PLACE (Continued on reverse side) Please set Crolled Customer Decrube
We have a many's Place
in system, from a city.
He explained many's other
Emxil He explained many's other
place is a and Location.
Place is a and Location.
To the
Antiscontine To the
To this Location It the
in a current FFL for 1st
in a current FFL for 1st ronic Version Available eiving the electronic version of the FFL Newsletmal additional information, should submit name, iil address to: FFLNewsletter@atf.gov. :wsletter will enable ATF to communicate es on a periodic basis.



Fulcher, Dell Marie

From:

Mail Delivery System [MAILER-DAEMON@AOL.com]

To:

ibcrazynate@aol.com

Sent:

Thursday, December 30, 2010 10:39 AM

Subject:

Relayed: Nathan Montoya - Remington Ref# 5041

Delivery to these recipients or distribution lists is complete, but delivery notification was not sent by the destination:

ibcrazynate@aol.com

Subject: Nathan Montoya - Remington Ref# 5041



November 9, 2010

Nathan Montoya 4011 Rangeview Dr. Cheyenne, WY 82001 Ph: 307-637-7253

Ref: #5041

Dear Mr. Montoya,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.


Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product **Service**". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700 Fax: 336-548-7872

enclosure





Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Drint	Paget
Print	Reset

Model Number: 77み	Serial Number: 71385092		
Are you the original owner?: X YES NO			
Name: Nathan Montoya	Date of Purchase: Sept or god 2007?		
Address (no	PO Boxes):		
4011 Rangeview Dr			
City: Cheyenne	State: WY Zip: 82001		
Phone (Daytime): 307 637 7253	Fax:		
E-mail Address:(if e-mail address is provided be sent)	man (in solid this principal to the principal decomposition (1990) (1990		
E-mail Address: I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: This year during artelept hunting scorsen, I got out of the trick to walk over a short hill. I got my rith out of the back seat, loaded the clip in the gun, and tried to load a round when I closed the bolt, with my left hand on the foreend of the rifle and my right hand operating the bolt, the gun fired. There was nothing near the trigger at all. It shot a hat through my triends glove compartment, broke some wiring hurnesses under the dash, put a note through the firewall, and a hole through the downpipe on the exhaust. This happend on Oct 8, 2010			
Ammunition I	nformation:		
Manufacturer: Renington winchester	Type: 130gr PSP 130gr Super-X		
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used:	Powder Weight:		
Case/Hull Used:	Primer Used:		
Bullet Type/Shot Size:	Reloader Used:		
Firearms Care (Cleaning and Lubrication):			

Brand of cleaning solution used: Reminston
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds) 50 rounds
Brand of lubricant used: Reminston
How often do you lubricate the bore? (Months or Number of rounds) 25 rounds
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES YES NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

11/08/2010 08:41 AM

11/05/2010 04:59 PM

5041

Reference # 101102-000105

Status Updated

Assigned To Administrators Dell -

Product Firearms

SLA Not specified

Queue CSR

Date Created 11/02/2010 06:27 PM

Initial Response 11/05/2010 04:59 PM

Last Updated 11/08/2010 08:41 AM

Customer SmartSense +2 (on -3 to +3 scale)

Staff SmartSense +1 (on -3 to +3 scale)

Remington 770

Discussion Thread

Customer (Jeremy Padgett)

Serial Number: 71385092

Caliber: .270
Friend's Name and Info:
Nathan Montoya
4011 Rangeview DR
Cheyenne, WY 82001
307 637 7253

From: info@remington.com To: impadg@hotmail.com

Date: Fri, 5 Nov 2010 16:59:12 -0400

Subject: Remington 770 [Incident: 101102-000105]

Response (Dell -)

Dear Mr. Padgett.

We would like the rifle to come into our Product Services Department at our factory for examination. Please reply back to me with the serial number of the rifle, caliber, your friend's mailing address and phone number. We would like to send a pre-paid shipping label for UPS to have the firearm come in. I will also include a form that needs to be filled out to let the examiner know exactly what happened, when this occurred and what you all are expecting.

Sincerely, Dell

Customer (Jeremy Padgett)

Hi

This will be kind of a long email to explain my problem.

11/02/2010 06:27 PM

I have been hunting and shooting for a long time. For 20 years I tried to get a close friend to hunt and shoot with my family and me and finally 3 years ago he borrowed a rifle from us and went hunting and liked it. Right away he wanted to buy his own rifle and ended up with a Remington 770 in .270. I am not personally a fan of the 770 but he didn't want to spend much money until he was sure he was going to continue hunting. I helped him sight in this rifle and it shot sub MOA consistently, which impressed me for the price of the rifle/scope

This last spring I bought a 700 VTR in .308 and had nothing but problems with it. After contacting Remington and sending it back, a new rifle was returned to me. I have nothing but good things to say about Remington and the customer service I recieved dealing with the VTR issue. I had almost talked my friend into a Sendero to replace his 770. Almost.

This year during antelope hunting season, my friend and me were getting out of the truck to walk over a short hill where we'd seen a herd of antelope. I got out with my rifle and shut my door. He got out then and grabbed his rifle out of the back seat, loaded the clip in his gun, and loaded a round. When he closed the bolt, with his left hand on the fore end and right hand operating the bolt, the gun fired. There was nothing near the trigger at all. I now have a hole through the glove box in my truck, a few broken wire harnesses, a hole through the firewall, and a big hole in the downpipe of my exhaust.

I've had a very good experience with my first Remington even though I'm a big fan of Savage. I'm not real sure about my friend now though, or myself for that matter as far as Remingtons go. Is this a known issue with the 770? Is there a fix? This gun has not been modified in any way. The deductible on my truck insurance is higher than the price to fix the holes in my truck. Can Remington help me pay to fix my truck?

Thanks, Jeremy Padgett 4111 Van Buren Ave Cheyenne, WY 82001 307-630-6410

Primary Contact

First Name: Jeremy Last Name: Padgett Organization:

Login: jmpadg@hotmail.com

Titie: Contact Type:

Email: jmpadg@hotmail.com

- Not gun owner

Email - Alternate #1: Email - Alternate #2:

> Office Phone: Mobile Phone:

http://remington.custhelp.com/cgi-bin/remington.cfg/php/admin/display/inc print.php?p si... 11/9/2010

Assistant Phone: Home Phone:

Street City State/Province Postal Code

Additional Information



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		11/9/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACK	4(10 lbs
PLEASE CHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXX
DESCRIPTION:	Ref# 5041 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Nathan Montoya
4011 Rangeview Dr.
Cheyenne, WY 82001
Ph: 307-637-7253

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR:

```
1 OF 1
               NOV 10, 2010 ALL CURR USD
ACT UT 10.0 LBS
4XX596 NOV 10, 2010
SVC GNDCOM
TRACKINGH 1Z4XX5969065674814
REF 1:NATHAN MONTGYA/CD/DMF
REF 2:5041/RIFLE
                                               SVC T/P USD
HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHROS
                                                 RS 0.50
                         COD 0 00
                                                 SD 0.00
 DV 0.00
DC 0.00
                                               SD 0.0-
SP 0.00
                         OCD 0.00
                                  0.00
                          PR
                                                     10.54
                                 PUB+HANDL ING
 AH 0.00
 TOT PUB CHG 10.54
```

