Remington Arms Co., Inc. Product Service Legal Case #:4562

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 195800 5/13/2010 5/17/2010 5/17/2010

Customer Information

Business Last Name Street City State Zip Age Contact Type First Name 4500 Baldwin Rd. W 248-209-4200 Bass Pro Auburn Hills 48326 Reporter Bass Pro MI

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

Ρſ

S

PD Cause:4038 Could Not Duplicate Concern

Concern: 1008 Fired on Bolt Closing

Unknown

C Fired on bolt closing

Dealer reported - Customer stated the rifle fired on bolt closing. dmf

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

Remington CF/BA 700/3006 SPR 27017 G6964876 CE 4/16/2010 8:56:11 AM

Date Purchased Where Purchased Accessories Original Owner

AMERICAN ROD & GUN SCOPE,RINGS,TWO PIECE BASE U

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date
Settlement APV APV

Per Ilion - Repair under warranty

Repair/Replacement Repair/Replacement
Cost Date

\$67.52 5/20/2010

5/20/10: Per Fred S. - Could not duplicate concern. Check over, replace tpa & function test to restore confidence in rifle - warranty. dmf

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		5/17/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		24" 3006 SPR
	Date Code		CE
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	7

h	ļ 		
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	· .
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Like new; Functioning	
Overall	Stock Condition	Like new; Functioning	SMALL DENT IN CHEEK PIECE
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Received	Bulged	False	
	Description		STANDARD XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.012
Sear	Notch	Like new; Functioning	
	Toota	Test Fired	False
Feeding Test	Tests	False	
	Condition	Like new; Functioning	
Trigger	Pull	Select	5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		SCOPE, RINGS, TWO PIECE BASE

Work Ticket # 06337 Date: 5/5//- SHIPPED MAY 20 PAIDBASS PRO SHOPS OUTDOOR WORLD Gunsmith Performance Center (GPC) Repair Work Ticket

4563

24"
ا/۴ کا ن لاچ
- 2

_		
	Send to GPC	(Store#):

This Section to be	Completed by the Custon	ier						
Customer Name: First	Name Last Name ・Oke ひょう おんしけ				Da	ytime Phone: 539 546 — 633	S	Home Phone:
Customer Street Address:	1700 Panilam CT	Ap 1 1405	Š.			lumbus		61 Zip: 1/404
Make/Model:	Aug Jew		fork To Be Completed: (Incl	lude Gunsmith C				
Serial Number:	Caliber/Gauge:		Property States	f sulfit e-	I , n Steiri		7	" , " , "
6.696 4076	30-076		armenter and a second			kapatan 1972 an ing Kabupatèn 1988.	Salah sa masa daga	The state of the s
COC	Completed by the Associa	tarak da kanan da ka		A CALL CONTRACTOR	romise Date:		B	stimated Repair Costs:
Requesting Store Gunsmith	n Firearms Repair Log# (Book-page	-line): <u>K()(</u>	<u> </u>		T.			<u> </u>
☐ Store Property? SKU: Requesting Store A&D Log Number:			I	nspection Notes:	•	The same of the sa		
Requesting Store Name and	d Number:				Lee	214 62181	of the state	Section 18 1 Section 18 18 Section 18 18 18 18 18 18 18 18 18 18 18 18 18
Shipped to GPC#:	Date Shipped:	UPS Trac	king#:	Contra 7 9x50 TOPE				
Print: Associate Name:	•-		248 209-4	/Dui: /	Associate Signatu	re: - 252	<	
I have reviewed the work-to	o-be-completed estimate and author						B. A.	
complete the above work. This Section to be	Completed by the Gunsm	ith Only			usromer Signatu		The second second	
Date Ordered	Part Ordered		Sour	rce		Status		Date Rec'd
	l _d ;							
					COU	ld not duy	plimate	CONCERN.
Assigned to Gunsmith:	CPC Fireness Parair Lastin	CDC Store A.S.	D.L#.	Ness	che	chover	haplack	TUA +
Assigned to Ounsmith:	GPC Firearms Repair Log#:	GPC Store A& (If Store Prope		Notes:	Fun	c tion th	ot to he	210155
Date Rec'd at GPC:	Date Rtn'd to Requesting Store:	UPS Tracking	#:			2 dencin	RIFLE	
OTT I	#		Item Description/	Work Performed		sporsely		Amount
			<u></u>					
Supply of the su	9648	\					SF	HPPED M. 20 FAID
				· · · · · · · · · · · · · · · · · · ·				W. A. Z. D. P. A. D. P. P. A. D. P. P. A. D. P. P. D. P.
Model: 7	00			Tau :				1000-100
			r:	Shipping	; :		Gran	d Total: \$
							The state of the s	等 。1200年世紀中國
			I the overall condition		Customer S	ignature at Time of F	Pick-Up:	Pick-Up Date:
RE(00195800	0	trigger lock has beer					
			COPY YELLOW - REPA	AIR TAG PINK –	CUSTOMER CLAIM C	HECK		