Remington Arms Co., Inc.
Product Service
Legal Case #:5313

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 212374 12/3/2010 12/6/2010 12/6/2010

Customer Information

Last Name Street **Business** First Name City State Zip Contact Type Age 3940 Elmore Ave Gander Mt 52807 W 563-344-8880 Gander Mt Davenport IA Reporter

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause: 4038 Could Not Duplicate Concern

Unknown

S Fired on safe release

Concern:1007 Fired on Safe Release

C

12/19/10 Per note with rifle, customer was hunting and flipped safety off and gun fired.cm

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl.

DOM

Remington

CF/BA

700/223 REM

85370

S6650147 CC 4/11/2008 10:40:15 PM

Date Purchased

Where Purchased

Accessories

Original Owner

50050147 CC 4/11/2000 10:40:15 11

CABELAS WHEELING DC / # 809 TWO PIECE BASE, SLING

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date

APV APV

Per Ilion, check, clean, test fire at no charge

Repair/Replacement Cost Repair/Replacement Date

63.42

12/19/2010

12/19/10 Per Ilion, could not duplicate. Trig assm functioning as designed. Check over, clean and test fire at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/6/2010
	Product Type		RF
	Action Type		A
	Assigned To]	T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 223 REM HB SS
	Date Code		CC
	Bore Plugged	False]
	Bulged	False]
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning]
	Firing Pin	Slightly Worn; Functioning]

Non-Remington Components	Description		TWO PIECE BASE,SLING
	Sub-Assembly	X-Mark Pro	
Trigger	Altered	False	
	Pull	Select	3.5#
	Condition	Like new; Functioning	
Feeding Test	Tests	False	
Sear		Test Fired	False
	Notch	Like new; Functioning	
	Lift	Select	.010
Safety	Sub-Assembly	Non-ISS	
	Function	Like new; Functioning	
	Description		STANDARD XMP SAFETY
Receiver	Bulged	False	
Overall	Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
	Stock Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Locking	Notch Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Block Condition	Select	
Extractor	Ext/Eject Test	False	
	Cut Condition	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Bolt	Stop	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	·
	Face	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	





Service Request Service Order # 6811

SHIPPED TO VENDOR/STORE:

Remington Arms Co FFL# 1-56-02461 870 Remington Drive

Madison, NC 27025-0700

Attn:

Date Shipped: 11/23/2010

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 5-42-163-01-0B-00771

Attn: Gun Parts Dept. 3940 Elmore Ave Davenport, IA 52807

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Rifle Type:

Serial Number: s6650147

Model: 700 Cal/Ga.: 223

Cased?:

DESCRIPTION OF ITEM RETURNED:

complete gun

REASON FOR RETURN:

Customer was hunting and flipped safted off and gun fired.

ATTENTION VENDOR

Please contact me with any questions or concerns.

Ben Seaman (563) 344-8880

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

Gander Mountain Company

Attn: Roy Christensen

6801 120th Ave Kenosha, WI 53140

盟S6650147

Model:

700



could not deplicate concern. T.A. FUNCTIONING AS DESIGNED. check over cleans rest line AT M/C wages My









