

Remington Arms Co., Inc.
Product Service
Legal Case #:6066

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
		3/30/2011					

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Ted	Macon	PO Box 585	Smithville	TX	78957		H 512-748-6038

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	shot hole in cab of truck	Cause:4079 Other - Unexamined		
S	slam fires	Concern:1008 Fired on Bolt Closing	Unknown	
C				

3/30/11 Per call from Macon, he has a 700 that was given to him by his parents years ago. It will slam fire or fire when closing the bolt. He quit using it because he shot a hole in the cab of his truck. Local gunsmiths have cleaned it and but it has still happened on occasion.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/30-06	25793	B6729522		
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTING GOODS INC 77003		Y			

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
	Repair/Replacement Cost	Repair/Replacement Date				

3/30/11 Mailing ARS and box (1206520).cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------

Case #	6066	Date of Call	3/29/11	Date of Incident		PreLit		Lit		Obs	
--------	------	--------------	---------	------------------	--	--------	--	-----	--	-----	--

Reporter name		Incident Name/Age	Ted Macon
address		address	
contact #'s		contact #'s	
email		email	

Injury	
--------	--

Medical Treatment	
-------------------	--

Alleged cause	
---------------	--

Firearm	Ser #	Cal	DOM	Orig owner?	When/Where purchased			
700	B6729522	30-06		Y	parents bought it for him			

Ammunition	Factory/Reload	Manuf	Caliber	Bullet type/wgt	Lot #	Additional info

Other Product	
---------------	--

Notes:	Slam firing, bolt close Quit using it b/c he shot hole in cab. Local gunsmiths cleaned it & it will work Sometimes Won't happen every time.
--------	---

Customer's Request	
--------------------	--

My actions/offers	box & ARS
-------------------	-----------

1206520



www.remington.com

Remington Arms Company, Inc.
870 Remington Drive
P. O. Box 700
Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	3/30/2011	REQUESTED BY:	chnsty
QUANTITY:	1	WEIGHT PER PACKAGE:	10
PLEASE CHECK ONE			
MEDIA			
COORDINATOR		xxx	
TO MAIL		I WILL MAIL	
DESCRIPTION:			
700 B6729522			

LABEL INFORMATION

MAIL LABEL TO:	Ted Macon PO Box 585 Mithville, TX 78957
RETURN ITEM TO:	Rem Prod Serv

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX586 MAR 31, 2011 ALL CURR USD 1 OF 1
SVC GND COM ACT WT 10.0 LBS
TRACKING# 1Z4XX5868065925267
REF 1: TED MACON/CD/CM
REF 2: 700/B6729522
HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRG: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHG 11.33 PUB+HANDLING 11.33