

Remington Arms Co., Inc.
Product Service
Legal Case #:5231

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
215421	12/19/2010	11/29/2010	1/3/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Raymond	Hixson	PO Box 41	Soddy Daisy	TN	37384		W 423-593-3056 C 423-364-3749

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:1007	Fired on Safe Release	Unknown	
C	FSR			

11/29/10: Customer called in. He stated he had FSR 2 yrs ago. No damage, No injury. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6724475	AY	3/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
	ROSKIN BROS MIDDLETOWN NY	TWO PIECE BASE	U			

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM program						

Repair/Replacement Cost	Repair/Replacement Date
\$60.40	1/14/2011

11/29/10: Sending ARS, ltr, form. df 1/14/11: Per Ilion - Could not duplicate concern. TA very dirty & sticky. Parts work sluggish. Replace TA, clean & test fire under BLM program - quote. I called cust. & he has mailed a check for payment. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/3/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

Cause	4838	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		AY
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	ACT DIRTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.009
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY, STICKY
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

CS 12.18.10

5231

22"
AY3/7
GA
009
COPY

November 29, 2010

Raymond Hixson
PO Box 41
Soddy Daisy, TN 37384
Ph: 423-593-3056

Ref: # 5231

Dear Mr. Hixson,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.


Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700
Fax: 336-548-7872

enclosure

Serial Number:

6724475

Model: 700



RE00215421

could not duplicate concern.
T.A. very dirty & sticky parts
work suggest. Replace TPA,
clean & test fire under BCP
for \$ 20.00 + ship

Quote

RECEIVED
JAN 05 2011

BY:

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025
Phone 800-243-9700 • www.remington.com

2007

Print

Reset

Model Number: <u>700</u>		Serial Number: <u>6724475</u>	
Are you the original owner? ☒ YES ☐ NO YES			
Name: <u>RAYMOND HIXSON</u>		Date of Purchase: <u>? in the 1975-1979</u>	
Address (no PO Boxes): <u>8593 DERRY BERRY LN</u>			
City: <u>HIXSON</u>	State: <u>TN</u>	Zip: <u>37343</u>	
Phone (Daytime) <u>(423) 593-3056</u>		Fax: <u></u>	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) <u>HIXSONtaxes@aol.com</u>			
E-mail Address: ☐ I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: <u>7yrs ago the rifle fired while being loaded</u> <u>I put the rifle away</u> <u>IN 2007 I got the rifle out + it did</u> <u>it again: FIRED while being loaded.</u>			
500 characters left			
Ammunition Information:			
Manufacturer: <u>Remington</u>		Type: <u>30.06 150 GRAIN</u>	
Other (i.e. bullet weight/type, shot size, powder): <u></u>			
Handload Information:			
Powder Used: <u></u>		Powder Weight: <u></u>	
Case/Hull Used: <u></u>		Primer Used: <u></u>	
Bullet Type/Shot Size: <u></u>		Reloader Used: <u></u>	
Firearms Care (Cleaning and Lubrication): <u></u>			

Brand of cleaning solution used:	Remington
How often do you clean the bore? (Months or Number of rounds)	At each use - once
How often do you clean the action? (Months or Number of rounds)	1 time per day after use
How often do you clean the trigger assembly? (Months or Number of rounds)	1 time per year
Brand of lubricant used:	
How often do you lubricate the bore? (Months or Number of rounds)	5 rounds / 1 time per day / use
How often do you lubricate the action? (Months or Number of rounds)	Each use - 1x per day 5 rounds
How often do you lubricate the trigger assembly? (Months or Number of rounds)	10 rounds
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? ☒ YES ☐ NO	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? N/A	
What were the services performed?	
Ship your INSURED firearm by either UPS or Parcel Post to:	
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoeffler Avenue Illion, NY 13357	
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper	

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



www.remington.com

Remington Arms Company, Inc.
870 Remington Drive
P. O. Box 700
Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	11/29/2010	REQUESTED BY:	Dell
QUANTITY:	1	WEIGHT PER PKG:	10 lbs
PLEASE CHECK ONE			
MEDIA COORDINATOR TO MAIL		I WILL MAIL XXXXXX	
DESCRIPTION: Ref # 5231 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Raymond Hixson PO Box 41 Soddy Daisy, TN 37384 Ph: 423-593-3056
RETURN ITEM TO Remington Arms Attn: Product Service Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XXS88 NOV 30, 2010 ALL CURR USD 1 OF 1
SVC GND COM ACT WT 10.0 LBS
TRACKING# 124XXS88806600347
REF 1: RAYMOND HIXSON/CD/DMF
REF 2: 5231/RIFLE

HANDLING CHARGE 0.00		SVC T/P USD	
SINGLE-PIECE PUB RATE CHRG:			
DV 0.00	CDD 0.00	RS 0.50	
DC 0.00	DGD 0.00	SD 0.00	
OH 0.00	PR 0.00	SP 0.00	
TOT PUB CHG 8.74	PUB+HANDLING		8.74

