Remington Arms Co., Inc. Product Service Legal Case #:5713

Case			

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 1/19/2011

Customer Information

Last Name Type Business First Name Street City State Zin Contact Age PO Box 981 Incident James E Wall Tellico Plains 37385 H 423-519-3256 TN

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

Pį

C

PD Fired on safety

Other - Unexamined Cause:4079 Concern: 1007 Fired on Safe Release

Unknown

release

1/19/11 Per call from Wall, he bought his 700 about 15 years ago 2nd hand. He was out hunting and when coming back in it was raining and sleeting so he got in his truck to unload the rifle. He pushed the safety off it fired and shot his brake lines and air conditioner. He was able to do it 3 more times but hasn't been able to since. He has never had the gun apart. He has the truck in for repair and bought the condenser 2nd hand for them to put in. He thinks it will cost about \$400.cm

Firearm Information

Mfg.

Type CF/BA

Model/Ga. 700/22-250

SKU 25825

Bbl. DOM Serial

B6540702 Remington Date Purchased Where Purchased Accessories Original Owner

N

SPORTS SOUTH INC 71115

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims

Release Date

Reimbursement

Cash Settlement

Reim. Date Cash Date APV APV

Repair/Replacement

Repair/Replacement

Cost

Date

1/19/11 Mailing ARS. Told him to send pictures of damage to truck and repair receipt when he ships the rifle.cm

Examination[Remington/CF/BA]

Sub-Part Code Comment



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

	1/19/2011 REQUESTED BY:	christy
QUANTITY:	1 WEIGHT PER PACKAGE	
REASECHECKIONEN MEDIA		ХX
COORDINATOR		
TO MAIL	I WILL MAIL	
DESCRIPTION		
,		
	700	

LABEL INFORMATION

MAIL LABEL TO:	James E. Wall PO Box 981 Tellico Plains, TN 37385
RETURN ITEM TO:	Rem Prod Serv

PUEASE/COMPLETE/AUL PARTIS/OF THIS FORM, AND SEND TO THE MEDIA COORDINATOR.

*****Internal Use Only****

700 Log Sheet - 2010 CNBC Story

Date: 1/19/11 CSR:
Is the customer calling as a result of the broadcast?YESNO
Initial tone/Attitude of the caller:
Angry at Remington Supportive of Remington
Angry at CNBC for airing Supportive of CNBC
Nature/Purpose of Call:
Calling to offer support (pro-Remington)
Inquisitive about Remington position
Calling to provide broadcast feedback
Customer Owns a Model 700:
Customer Owns a Model 700: General concern of safety with personal model 700 Le got in the truck to unload it.
seeking company feedback regarding direction/use of personal Model 700
Leclaims they experienced a "safety" related issue with their personal Model 700
has not experienced a problem but wants firearm inspected (fill out address) send to an RARC
If the customer references any concerns or problems experienced in relation to the operation of the safety of the firearm, they should be advised to return it to (Product Service, Ilion NY).
Did they agree to return it to the factory? YES NO 15/15. In Ahand
Consumer Name: Jakes EWall 700 22-20 FSR
Address: POBOX 98/ Tellico plains 37385 Asst 1st time it happened. Phone: 423-519-3266 Serial #: B 6540702 1985 since all condition ***Send an ARS label*** The consumer Name: Jan 1985 since all condition ***Send an ARS label*** The consumer Name: Jan 1985 since all condition ***Send an ARS label*** The condition The condition of the condition
Tellico phoins 37385 host 1st time it hypered
Phone: 423-519-3266 with Shot broke lives
Serial #: 18 6540702 1985 SIND OIL Condition
Send an ARS label - never had quagrant,
Send au ARS label Comments: ARS Dought Condenser 2 had hand