

Remington Arms Co., Inc.
Product Service
Legal Case #:5672

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
222137	2/4/2011	1/17/2011	2/7/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Walter Neal	Ward	67 Pamela Dr	Monroeville	AL	36460		H 251-238-1321

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4015 Improper Maintenance		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

1/17/11 Per call from Ward, his cousin gave him this Model 700 ADL about a year ago and it fires when you release the safety.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	G6599809	WA	8/14/2006 4:56:58 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACADEMY CORP		N			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA no charge, 1/2 price for shipping and test						
	Repair/Replacement Cost	Repair/Replacement Date				
	42.40	2/10/2011				

1/17/11 Mailing box (1178165) and ARS.cm 2/9/11 Spoke with Ward and I will remove the charge for the trigger as a gesture of goodwill. He will pay the shipping and test charges, COD.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination:	Examiner		B.TRAVIS
	Exam Date		2/7/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 270 WIN
	Date Code		WA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown	Slightly Worn;	

	Condition	Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Not Functioning	RUST ON BBL UNDER STK
	Sock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M700 SAFETY
	Function	Like now; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	--Select--	010
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	VERY DIRTY. TRIG BINDS WILL NOT RETURN PROPERLY WILL FOLLOW DOWN
	Pull	--Select--	2#
	Altered	False	
	Sub-Assembly	M700 Non-Bolt Lock	


NOTE: Please complete and print this form, and then include it with your firearm.

22"
WA 8/06
2#
1010

Model Number: <u>Remington 700</u>		Serial Number: <u>G6599809</u>	
Are you the original owner? ☐ YES ☒ NO			
Name: <u>Walter Vard</u>		Date of Purchase: <u>9/21/09</u>	
Address (no PO Boxes): <u>67 Pamela Drive</u>			
City: <u>Monroeville</u>		State: <u>AL</u>	Zip: <u>36960</u>
Phone (Daytime): <u>251-238-1321</u>		Fax: _____	
E-mail Address (if e-mail address is provided, notification of receipt and shipment will be sent): _____			
E-mail Address: _____			
☐ I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence:			
<u>I was hunting on 1/3/10. I had a shot so I flipped the gun on fire and it fired. Without touching the trigger. So I repeated the same problem 2 times, and it did it both times.</u>			
500 characters left <u>C</u>			
Ammunition Information:			
Manufacturer: <u>Remington</u>		Type: <u>Core-Lock</u>	
Other (i.e. bullet weight/type, shot size, powder): <u>130gr</u>		FEB 1 2011	
Handload Information:		BY: _____	

G6599809

Model: 700



RE00222137

Powder Weight:	_____
Primer Used:	_____
Reloading Used:	_____

Will follow down. T.A. is very dirty
TRIG. is binding. Up to TPA, clean
& rest fine at 1/2 normal cost.

Quote



www.remington.com

Remington Arms Company, Inc.
870 Remington Drive
P. O. Box 700
Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	1/17/2011	REQUESTED BY:	christy
QUANTITY:	1	WEIGHT PER PACKAGE:	10
☒ PLEASE CHECK ONE MEDIA COORDINATOR TO MAIL		☐ I WILL MAIL ☒ XX	
DESCRIPTION: 700			

LABEL INFORMATION

MAIL LABEL TO:	Walter Neal Ward 67 Pamela Dr Monroeville, AL 36460
RETURN ITEM TO:	Rem Product Service

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 JAN 18, 2011 ALL CURR USD 1 OF 1
SVC GND COM ACT WT 10.0 LBS
TRACKING# 124XX5968066375796
REF 1:WALTER NEAL WARD/CD/CM
REF 2:700

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD
DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AM 0.00 PR 0.00 SP 0.00
TOT PUB CHG 10.00 PUB+HANDLING 10.00

