

Remington Arms Co., Inc.
Product Service
Legal Case #:4971

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
215512	12/19/2010	11/4/2010	1/3/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Edwin	Batchelder	175 Stillwater Bridge Rd.	Schaghticoke	NY	12154		H 518-753-4221 W 518-429-1519

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Concern:1007 Fired on Safe Release			
C	FSR			

11/4/10: Customer called in. He stated that he has been looking on the Internet & saw that we had a "recall". He had a FSR while dry firing rifle. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial Bbl.	DOM
Remington	CF/BA	7/7MM-08	24786	7750760 CT	4/26/1999
Date Purchased	Where Purchased	Accessories	Original Owner		
	AMCHAR WHOLESALE INC	TWO PIECE SCOPE BASE,BOTTOM HALF OF RINGS	U		

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/7/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair						

Repair/Replacement Cost Repair/Replacement Date

11/4/10: Sending ARS, ltr, form, box. Box order# 1155657. df 1/9/11: Per Ilion - Will follow down. TA rusty & set screws altered. Replace TA, clean & test fire @ 1/2 normal cost - quote. df 1/10/11: I spoke w/cust. He apprvd quote & pd by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		1/3/2011
	Product Type		RP
	Action Type		A
	Assigned To		T. NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		18.5" 7MM08 REM
	Date Code		CT
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ex/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/7 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	RUSTY
	Pull	---Select---	N/A
	Altered	True	SET SCREWS ALTERED,SEAR ENGAGEMENT TO FAR IN
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		TWO PIECE SCOPE BASE,BOTTOM HALF OF RINGS

Remington®

18.5
CT 4/99

4971

November 4, 2010

Edwin Batchelder
175 Stillwater Bridge Rd.
Schaghticoke, NY 12154
Ph: 518-753-4221

Ref: # 4971

Dear Mr. Batchelder,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700
Fax: 336-548-7872

RECEIVED
JAN 05 2011


BY:

enclosure

Serial Number:

7750760

Model: 7



RE00215512

will follow down. T.A. rusty &
set screws altered. Replace
TDA, clean & test fire at
1/2 normal cost.

Quote.

Model Number: MODEL SEVEN 7mm08		Serial Number: 7750760	
Name: Edwin Batchelder		Date of Purchase: 08	
Address (no PO Boxes): 175 Stillwater Bridge Rd			
City: Schaghticoke		State: NY	Zip: 12154
Phone (Daytime): 518 429-1519		Fax:	
E-mail Address:			
Please describe your problem: FIRING PIN ENGAGES AS SOON AS SAFETY IS IN OFF POSITION. 500 characters left			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
☒ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. Print Reset			

Remington.

www.remington.com

Remington Arms Company, Inc.
870 Remington Drive
P. O. Box 700
Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	11/4/2010	REQUESTED BY:	Dell
QUANTITY:	1	WEIGHT PER PACKAGE:	10 lbs
☒ PLEASE CHECK ONE			
MEDIA			
COORDINATOR		I WILL MAIL	
TO MAIL		XXXXXX	
DESCRIPTION: Ref# 4971 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Edwin Batchelder 175 Stillwater Bridge Rd. Schaghticoke, NY 12154 Ph: 518-753-4221
RETURN ITEM TO Remington Arms Attn: Product Service Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX598 NOV 4, 2010 ALL CURR USD 1 OF 1
CVC 680COM RET WT 10 0 163
FROM INCH 124X505/360S49246
REF 1 EDWIN BATCHELDER/COORDNF
REF 2 4971/RIFLE

HANDLING CHARGE 0 00
STABLE/Piece Price Rate Charge
BY 0 00 CDD 0 00 SVC T/P USD
DO 0 00 DCD 0 00 RT 0 50
AT 0 00 PR 0 00 SG 0 00
TOT PUB CHG 7 24 PMS HANDLING 7 24

