

Remington Arms Co., Inc.
Product Service
Legal Case #:5601

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
218184	1/10/2011	1/11/2011	1/11/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Academy Sports and Outdoors		Academy Sports	2810 John Hawkins Pkwy	Hoover	AL	35244		W 205-403-6145

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

2/3/11 Per note with firearm, gun fired when safety was released.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	770/3006 SPR	85653	71453250	OC	7/22/2008 6:38:29 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACADEMY CORP	SCOPE BASE	U			

CONCERN-FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/770/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test fire at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	42.36	2/3/2011				

2/3/11 Per Ilion, could not duplicate concern. To restore confidence in rifle, will replace TPA, clean, test fire at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/11/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

Cause	4038	Could Not Duplicate Cause	
Barrel	Description		22" 3006 SPR SS
	Date Code		OC
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Missing	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/770 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	HAS EXCESS PREPLAY
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	Other Remington	

Customer Firearm Repair - Info for Manufacturer/Repair Center

Today's Date 12/23/2010

Completed By Anna Willis

Manufacturer/Repair Center Information:

Manufacturer/Repair Center Address Remington Arms Corporation, Inc.
Attn: Arms Service Division/Repairs
14 Hoefler Ave.
Ilion, NY 13357
Phone Number 1-800-243-9700
Website www.remington.com

Notes 0

Serial Number 71453250

Model Model 770

Type of Firearm Rifle

Caliber/Gauge 30.06

SKU ~~47700856837~~ 14256770

Reason for Repair Gun fired when safety was released


RA # (if applicable) 0

Return Address Please return the firearm to the following address once the repair is complete:
Academy Sports + Outdoors
Attention: MOD
2810 John Hawkins Pkwy
Hoover, AL 35244

Store Phone Number 205-403-6145

Serial Number: 71453250


Model: 770



RE00218184

could not duplicate concern.
To restore confidence in
rifle will replace TPA, clean
& test fire at 1x/c

warranty



BY: _____

