

Remington Arms Co., Inc.
Product Service
Legal Case #:3665

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
218882	1/14/2011	1/17/2011	2/4/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Alice	Curry	102 Ruby Ln.	Longview	TX	75604		H 903-297-2119
Incident		Joel	Curry	same address					H same phone #

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern:100% Fired on Bolt Closing		Unknown	
C	FBC			

Customer sent gun in with note. Stated the Model 770 has been the worst rifle. Gun misfire while closing bolt and the whole bolt came out while ejecting a shell. Does not want this rifle back. Wants a refund or different rifle. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	770/270 WIN	85632	71526774	CD	4/2/2009 8:25:27 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAL-MART SUPERCENTER 0398 SCOPE BASE		U			
CONCERN:MISFIRED ON SAFETY PUSHING BOLT FORWARD						

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Remington/770/CF/BA						
Replace w/27361 in exchange						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$193.57	2/4/2011				

2/4/11: I spoke with Joel Curry. He is an adult. We agreed to a Model 700 SPS, 270 Win as replacement in exchange. He will call me back with info on dealer to ship to. df 2/16/11: Dealer faxed over FFL. Solid Pawn in Longview, TX. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		1/17/2011
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE

Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 270 WIN
	Date Code		CD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Missing	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/770 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	DIRTY
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	Other Remington	

Federal Firearms License
(18 U.S.C. Chapter 44)

COPY

In accordance with the provisions of Title I, Gun Control Act of 1968, and the regulations issued thereunder (27 CFR Part 478), you are licensed to engage in the business specified in this license, within the limitations of Chapter 44, Title 18, United States Code, and the regulations issued thereunder, until the expiration date shown. See "WARNINGS" and "NOTICES" on reverse.

Direct ATF ATF - Chief, FFLC
Correspondence To 244 Neady Road
Martinsburg, WV 25405-9431

License
Number

3-75-183-02-3F-05423

Chief, Federal Firearms License Center (FFLC)

Expiration
Date

June 1, 2013

Name
SOLID PAWN

Licensee Address (Changes? Notify the FFLC of any changes.)
521 N HIGH ST
LONGVIEW, TX 75801

Type of License
D2-PAWNBROKER IN FIREARMS OTHER THAN DESTRUCTIVE DEVICES

Purchasing Confirmation Statement

The licensee named above shall use a copy of this license to assist a transfer of firearms to verify the identity and the licensed status of the licensee as provided by 27 CFR Part 478. The licensee shall also keep a copy of this license on file. A faxed, scanned or e-mailed copy of the license with signature attached to an original signature is acceptable. The signature must be that of the Federal Firearms Licensee (FFL) or a responsible person of the FFL. Verify that this is a true copy of a license issued to the licensee named above to engage in the business specified above under Type of License.

Mailing Address (Changes? Notify the FFLC of any changes.)

CORONA SKY LLC
SOLID PAWN
521 N HIGH ST
LONGVIEW, TX 75801

Licensee/Responsible Person Signature

Larry Clark

Printed Name

Signature

1-03-2011

Date

ATF Form 2 (3-10-11)
Revised September 2008

Attn: Dee
For Joel Curry
Remington 8700

X


5665

22"
C04/09
4.5#

Serial
Number

71526774

Model: 770



RE00218882

RECEIVED
JAN 19 2011

BY:.....

Remington Model 770 S/N 71526774

Alice P. Curry / Tel

102 Ruby Ln

Longview, TX 75604-1148

This Remington Modell 770 has been the worst gun I have ever brought in my life. This gun has misfired on safety while pushing the bolt forward. This time I went to eject a shell w/ the bolt carrier down and the whole bolt came out. The top swivel has broken so I can't put a sling on it. Now with the bolt carrier up I can't get the bolt back in. I do not want a Model 770 I either want full refund or a different Model of .270 caliber I paid 379.98 and it has been horrible!

Thanks

Alice Curry

Alice P. Curry

102 Ruby Ln

Longview, TX 75604-1148

WMAHS m/770 SPS .270

903-297-2119

