

Remington Arms Co., Inc.
Product Service
Legal Case #:6029

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
226481	3/22/2011	3/23/2011	3/23/2011				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Gander Mt		Gander Mt	4275 Haines Rd	Hermantown	MN	55811		W 218-786-9800

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
FI				
PD				
S	Fires when safety is released	Cause:4006 Concern:1007	Altered Adjustments or Components Fired on Safe Release	Unknown
C				

3/31/11 Per note with rifle, striker follows bolt when closing and fires when coming off of safety.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	721/300 H&H MA	n/a	291225	LZZ	2/1/1953
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE,RINGS,TWO PIECE BASE	U			

CONCERN:FBC,FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean and test fire under BLSM program						
	Repair/Replacement Cost	Repair/Replacement Date				
	55.83	3/31/2011				

3/31/11 Per Ilion, trigger asm screws altered. Bolt stop missing. Improper parts used on trigger asm. Replace TPA, clean and test fire under BLSM program for \$20 + S&H.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		3/23/2011
	Product Type		RF
	Action Type		A

	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE,RINGS,TWO PIECE BASE



6029

Service Request

Service Order # 7657

26"
L222/
15"

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00727

14 Hoefler Ave

Ilion, NY 13357

Attn:

Date Shipped: 03/14/2011

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 3-41-137-01-3b-01217

Attn: Gun Parts Dept.

4275 Haines Road

Hermantown, MN 55811

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Type: Rifle

Serial Number: 291225

Model: 721

Cal/Ga.: 300 H&H

Cased?: ☐

DESCRIPTION OF ITEM RETURNED:

Remington 721 with scope

REASON FOR RETURN:

Striker follows bolt when closing, and fires when coming off of safety

ATTENTION VENDOR

Please contact me with any questions or concerns.

Shayne Schelinder

(218) 786-9800

105
43
17.64
27. -
20. -
17.50
15. -
97.62
-41.80
55.83

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS


Forward all invoices to: Gander Mountain Company
Attn: Cindy Kilbride
180 E. Fifth Street Suite 1300
St. Paul, MN 55101

RECEIVED
MAR 23 2011

BY:

291225

Model: 721



RE00226481

T.A. set + screws A / head
Bolt stop missing. Improper parts
used on T.A. Replace TPA,
clean & test fire under BL
for \$ 20.00 + ship
Quote



