

Remington Arms Co., Inc.
Product Service
Legal Case #5841

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
222285	2/7/2011	2/8/2011	2/8/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter Academy	---	Academy	1557 COTTON EXCHANGE	PRATTVILLE	AL	36066			W 334-290-6600

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

Dealer sent gun in for consumer. Dealer stated "flipped off safety and firearm discharged". df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	27119	G6913591	RD	11/2/2009 10:13:49 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ACADEMY SPORTS & OUTDOORS		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV

Per Hion - Check over completely - warranty

Repair/Replacement Cost	Repair/Replacement Date
\$59.50	2/22/2011

Per Hion - Could not duplicate concern. TA functions as designed. Check over completely, clean & test fire - warranty. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/8/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE

Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 243 WIN
	Date Code		RD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	X-Mark Pro	



Customer Firearm Repair - Info for Manufacturer/Repair Center

Today's Date 1/29/2011

Completed By Ben Hooker

5841

Manufacturer/Repair Center Information:

Manufacturer/Repair Center Address Remington Arms Co.
Attn: Arms Service Division/Repairs
14 Hoefler Ave.
Ilion, NY 13357

Phone Number 1-800-243-9700

Website www.remington.com

Notes 0

Serial Number G6913591

Model 700

Type of Firearm Rifle

Caliber/Gauge 243

SKU 15619174

Reason for Repair Flipped off safety and firearm discharged

RA # (if applicable) 0

Return Address Please return the firearm to the following address once the repair is complete:
Academy Sports + Outdoors
Attention: MOD
Ben Hooker
0


Store Phone Number 334-290-8600

24"
RD 11/00
4#

Serial Number

G6913591

Model: 700



RE00222285

could not duplicate concern.
F.A. functions as designed.
checkdown completely, clean
TEST fire

WASP ANDY
RECEIVED
FEB 10 2011

BY _____

