

Remington Arms Co., Inc.
Product Service
Legal Case #:5745

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
220150	1/21/2011	1/24/2011	1/24/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Dicks Sporting Goods	---	Dicks Sporting	2 Grand Corner Ave.	Gaithersburg	MD	20878		W 301-947-0200

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
FI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Concern: 1025	Unexplained Discharge - No Mention of Safety Position	Unknown	
C	Fires without pulling trigger			

Dealer sent rifle in for customer. Customer stated rifle fired without pulling trigger. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	85380	G6674403	OB	7/20/2007 5:34:46 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	DICK S SPORTING GOODS	SCOPE,RINGS,TWO PIECE BASE	U			

CONCERN:FIRED WITHOUT PULLING TRIG

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Check over completely @ n/c						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$27	2/9/2011				

Per Ilion - Could not duplicate concern. TA functions as designed. Check over completely, clean & test fire @ n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B TRAVIS
	Exam Date		1/24/2011

Examination	Product Type	RF
	Action Type	A
	Assigned To	T.NAGLE
Cause	4038	Could Not Duplicate Concern
Barrel	Description	24" 3006 SPR
	Date Code	OB
	Bore Plugged	False
	Bulged	False
	Fired	False
	Fired while Obstructed	
Bolt	Muzzle/Crown Condition	Like new; Functioning
	Firing Pin	Like new; Functioning
	Shroud	Like new; Functioning
	Face	Like new; Functioning
	Handle	Like new; Functioning
Extractor	Stop	Like new; Functioning
	Condition	Like new; Functioning
	Cut Condition	Like new; Functioning
Locking	Ext/Eject Test	False
	Block Condition	---Select---
	Lug Condition	Like new; Functioning
Overall	Notch Condition	---Select---
	Exterior Condition	Like new; Functioning
	Stock Condition	Like new; Functioning
Receiver	Fore End Condition	---Select---
	Condition	Like new; Functioning
Safety	Bulged	False
	Description	XMP SAFETY
	Function	Like new; Functioning
Sear	Sub-Assembly	Non-ISS
	Lift	---Select---
	Notch	Like new; Functioning
Feeding Test	Tests	Test Fired
		False
Trigger	Condition	Like new; Functioning
	Pull	---Select---
	Altered	False
	Sub-Assembly	X-Mark Pro
Non-Remington Components	Description	SCOPE,RINGS,TWO PIECE BASE

5745

24"
037/07
3.5"

Dear Sir or Madam,

The firearm listed below is being return for repair or replacement due to the defect listed. Please call us with any question concerning this transaction.

DATE: 1-8-11
VENDOR NAME: Remington
MODEL NUMBER: 700
ACTION: Bolt
BARREL: _____
FINISH: _____
CAL/GA: 30-06
SERIAL NUMBER: G6674403


DISCRIPTION OF DEFECT

Misfires. Fires without pulling
trigger

REPLY TO: DICKS SPORTING GOODS
Store 414 Washingtonian
2 Grand Corner Ave
Gaithersburg, Maryland 20878
301-947-0200
ATTN. LODGE DEPT.

RECEIVED
JAN 25 2011
BY: _____

G6674403
Model: 700



RE00220150

could not duplicate concern
T.A. Functions as Designed.
check over completely, clean
& test fire

N/C
unhappy



FIREARM RECEIPT FORM

29437

DROP OFF DATE 1-8-11 PICK UP DATE _____ STORE NUMBER 414

NAME F. J. ...

ADDRESS 1234 ...

TELEPHONE # ...

IDENTIFICATION TYPE ... NUMBER P233261009526

EXPIRATION DATE 07/03/2015 DATE OF BIRTH (D.O.B.) 07/03/1942

MANUFACTURER AND IMPORTER Remington

MODEL 700 CALIBER/GAUGE 30-06

SERIAL # 66674403

REASON FOR RETURN/DEFECTS: Fire by itself, misfire

ASSOCIATE SIGNATURE DROP OFF _____ PICK UP _____

CUSTOMER SIGNATURE DROP OFF _____ PICK UP _____

CUSTOMER DROPPING OFF AND PICKING UP THE FIREARM MUST BE THE SAME PERSON.
PLEASE ALLOW 8-12 WEEKS FOR RETURN OF THE FIREARM.

PART 1 - STORE PART 2 - CUSTOMER PART 3 - ATTACH TO FIREARM

