

Remington Arms Co., Inc.
Product Service
Legal Case #:5542

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
215411	12/19/2010	1/5/2011	1/5/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Gander Mt		Gander Mt	3970 SW 3rd St #101	Ocala	FL	34474		W 352-351-6186
Incident		Douglas	Jochumsen	6655 SW 106th Ln	Ocala	FL	34476		H 352-873-9392

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Cause:4038 Fired when safety was pushed off	Could Not Duplicate Concern Concern:1007 Fired on Safe Release	Unknown	
C				

1/17/11 Per note with rifle, sent back to us for safety and trigger issues. Fired when safety was pushed off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl	DOM
Remington	CF/BA	700/270 WIN	85373	G6801141	EC	10/3/2008 11:29:07 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAL-MART SUPERCENTER 0697	TWO PIECE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, check over completely, clean, test fire at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	59.50	1/17/2011				

1/17/11 Per Ilion, could not duplicate concern. Trigger assm functioning as designed. Assm is dirty and sticky. Check over completely, clean, test fire at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment

Examination	Examiner	B. TRAVIS	
	Exam Date	1/5/2011	
	Product Type	RF	
	Action Type	A	
	Assigned To	T. NAGLE	
Cause	4038	Could Not Duplicate Concern	
Barrel	Description	24" 270 WIN	
	Date Code	EC	
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description	XMP SAFETY	
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	DIRTY, STICKY
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description	TWO PIECE BASE	



Service Request
Service Order # 1474

24"
2010/11
4th
10/11

5542

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726
14 Hoefler Ave

Ilion, NY 13357

Attn:

Date Shipped: 12/13/2010

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 1-59-083-01-18-07897
Attn: Gun Parts Dept.
3970 SW 3rd Street #101
Ocala, FL 34474

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.
Model: 700

Type: Rifle
Cal/Ga.: .270

Serial Number: G6801141
Cased?: ☐

DESCRIPTION OF ITEM RETURNED:

Remington/700/270/Rifle
Serial #: G6801141

REASON FOR RETURN:

Send back to remington for safety and trigger issues.

27
15
17.50
59.50

ATTENTION VENDOR

Please contact me with any questions or concerns.

Ashton Goodson
(352) 351-6186

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence.

SHIP TO ABOVE ADDRESS


Forward all invoices to: Gander Mountain
Attn: Cindy Kilbride
180 E. Fifth Street Suite 1300
St. Paul, MN 55101

RECEIVED
JAN 06 2011
BY:

shpd. 1/13/11

G6801141

Model: 700



RE00215411

could not duplicate concern.
T.A. FUNCTIONING AS DESIGNED.
ASSM IS DIRTY + STICKY. CHECK
over completely, clean + test
fine or N/C
WARRANTY

(reset Trigger pull screw)

270

Gunsmith SO# 1474

GM#354 - Ocala
3970 SW 3rd Street #101
Ocala, FL 34474
(352) 351-5185
Gunsmith: Default Gunsmith



*** Firearm Copy ***

CUSTOMER INFORMATION:	
Home #:	(352) 873-9392 Day #:
Name:	Jochumsen, Douglas
Address:	6655 SW 106th Ln
Ocala, FL 34476	

DATES:	
Acquired:	12/11/2010
Apx Comp:	
Completed:	
Cust. Called:	
Disposed:	

FIREARM INFORMATION:			
Manufacturer: Remington Arms Co Inc.	Type: Rifle	Serial Number: G6801141	
Model: 700	Cal/Ga.: .270	Firearm Value: \$0.00	Cased? ☐

Description: Blued camo stock Condition: good

Service Description: Send back to Remington for safety and trigger issues. Fired when safety was pushed off

LABOR		
UPC	Description	Amount
Labor Sub Total:		

Labor Notes:

PARTS		
UPC	Description	Amount
Parts Sub Total:		

Parts Notes:

* Estimate Only * Customer must pick up their own Firearm	TOTALS
	Labor Sub Total:
	+ Parts Sub Total:
	Total:
	- Deposit Amount:
	Amount Due:

*** Does not include Sales Tax ***

The Child Safety Lock Act of 2005 states "it is unlawful for a dealer to sell, deliver, or transfer any handgun to any person, other than another licensee, unless the transferee (buyer) is provided with a secure gun storage or safety device for that handgun." Gander Mtn. will be providing trigger locks to all transferee's (buyer's) for a nominal fee. Transferee's may also supply their own secure gun storage or safety device.

SIGNATURE: Doug Jochumsen DATE: 12-11-10

