Remington Arms Co., Inc. **Product Service** Legal Case #:6087

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 4/5/2011 229221 4/19/2011 4/20/2011 4/3/2011

Customer Information

Last Name Street City Contact Type Business First Name State Zip Age Phil 1302 S. 3rd St Chickasha OK 73018 H 405-224-1510 Incident Haney

Incident Information

Medical Medical Claims Codes Repair Est. Treatment Status

PΙ

PD Could Not Duplicate Concern

 $\begin{array}{c} \text{Concern:1006} \\ \text{OFF} \end{array}$ Unknown Barely touched trigger

and it fired

C

4/5/11 Per call from Haney, he bought this rifle about a year ago and has shot it with no problems in the past. Sunday he had it out and the trigger locked up. He couldn't open the bolt. The safety was off. He laid it down on it's side and was working the bolt. He barely touched the trigger trying to get the bolt to release and it fired.cm

Firearm Information

SKU **DOM** Mfg. Type Model/Ga. Serial Bbl.

84371 CF/BA 700/300 WIN MA G6891302 WD 8/7/2009 6:41:41 PM Remington

**Original Owner Date Purchased** Where Purchased Accessories Y

1/5/2010 RSR GROUP TEXAS, INC.

CONCERN: WENT OFF BARELY TOUCHING TRIG

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Cash Cash Settlement Release of Claims Release Date Reimbursement Date Date Settlement APV APV

Per Ilion, fit new TPA, clean, test at no charge to restore confidence

Repair/Replacement Repair/Replacement

Cost Date 4/28/2011 52.88

4/5/11 Mailing ARS.cm 4/28/11 Per Ilion, could not duplicate concern. To restore confidence in rifle will fit new TPA, clean, test at no charge under warranty.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		4/20/2011
	Product Type		RF

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6087&Type=Case

4/28/2011

	Action Type	<del></del>	A
	Assigned To	<del></del>	T.NAGLE
Cause	4038	Could Not Duplicate Concern	I.NAGEL
Cause		Could Not Duplicate Concern	26" 300 WIN MAG
	Description Date Code	<del></del>	WD
		False	[WD
	Bore Plugged		
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.011
	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
	Pull	Select	4#
Trigger	Altered	False	
	Sub-Assembly	X-Mark Pro	

## Remington

26 0 8/0 WD 8/0 UT

6087

April 5, 2011

Phil Haney 1302 S. 3<sup>rd</sup> St. Chickasha, OK 73018

Subject: #6087, Model 700


Dear Mr. Haney,

Thank you for your patience. Enclosed is the UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the boxes with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com



G6891302 Model: 700



RE00229221

could not duplicate concern. 27
To restone confidence in 25.88
Rifle will Rit new TPA 25.88
cleans Test Fire At N/c 52.88
warpanly

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

	<del></del>	,
Model Number: 700 SAS	Serial Number: 6689	1302
Are you the original owner?: YES NO		
Name: Phillip Haney 0	Date of Purchase:	05-2010
Address (no PO Boxes): 1302 5 3rd	Str.	
city: Chickasha	State: OK	Zip: 173018
Phone (Daytime): 405-224-/510	Fax:	
E-mail Address:(if e-mail address is provided, notification		e
sent) + MEC1.4@ Sbcglobal. Net		
E-mail Address:		
I would like to receive tuture e-mail updates from He		
Please describe your problem and date of occurrence		
Trigger + Bol+ Hungs		
14 · ·		انطنه : :
Lockedwith Shafety off		
Then with oft with very lig	ht parclow Trigg	:en
And Andrew Palmers		<u>.</u>
Praymin Andrews		÷
Andre experience		
		Notice of the Control
500 characters left		
Ammunition Information:		
Ammunitati momason.		
Manufacturer: Holandy	Type: 1656 1411	SST Interlock
Other (i.e. bullet weight/type, shot size, powder):		
Other (i.e. builet weighttype, and size, power).	-	
Handload Information:		
Powder Used:	Powder Weighi:	
Case/Huil Used:	Primer Used:	
Bullet Type/Shot Size:	Reloader Used:	Company of the Compan

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used: Hoppes
How often do you clean the bore? (Months or Number of rounds) of ter 20 rounds
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: Reming for
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds) 20 / 0 lands
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?  YES NO
When was the last time that your firearm was serviced by a Remington authorized repairmen/gunsmith?)
What were the services performed?) //one
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
<b>WARNING:</b> DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.

* C					6	runday		
Case #	6087	Date of Call	1/5/11	Date of Incident	43/11	PreLit Lit	Obs	
Reporter name address				Incident Name/Age address	Ph	11/ Han 302 S.	grds	7
contact #'s				contact #'s	CLI	ckasha -224-1	OKT	3818
email				email	903	- ddy - 7.	<i></i>	
Injury								
Medical Treatment								
Alleged cause								
Firearm	Ser#	Cal	DOM	Orig owner?	When/W	here purchased		
760	66874127					lyr.cld		
Ammunition	Factory/Reload	Manuf	Caliber	Bullet type/wgt	Lot#	Additional info		
Other Product	The A	rager 1	locked i	ip. Con	inld Lt	t open b	olt.	House
	The trigger locked up. Couldn't open bott. it Safety off, Turned it on its side, laid down tit fired when he touched trigger						rigger	
heard dealer-	Sold it	Vov/Dec	2. 2009					
backgrow Notes:	Has shot	titb	etore					
Customer's Request								
My actions/ offers								



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:	4/5/2011	REQUESTED BY:	christy
QUANTITY:	1	WEIGHT PER PACKAGE:	10
PLEASE CHECK ONE:			
MEDIA			
COORDINATOR			XXX
TO MAIL		I WILL MAIL	
DESCRIPTION:			
	700		
G6874127			

## LABEL INFORMATION

MAIL LABEL TO: Phil Haney
1302 S. 3rd St
Chickasha, OK 73018
405-224-1510

RETURN ITEM TO: Remington Prod Service

## PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

APR 5, 2011 ALL CURR USD ACT UT 10.0 LBS 1 OF 1 4XX596 4XX596 SVC GNDCOM TRACKING# 1Z4XX5969066635588 REF 1:PHIL HANEY/CD/CM REF 2:700/G6874127 HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: RS 0.50 SD 0.00 0.00 COD DV 0.00 DC 0.00 0.00 DGD SP 0.00 PR 0.00 10.18 PUB+HANDLING AH 0.00 TOT PUB CHG 10.18



