PrintDisplay Page 1 of 2

> Remington Arms Co., Inc. Product Service Legal Case #:5489

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 3/15/2011 12/22/2010 4/8/2011 225858

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact H 512-968-8270

3501 Rocky Creek Rd LaGrange TX 78945 Incident Michael Knapik

E mmeknapik@up.com

Incident Information

Claims Repair Est. Medical Treatment Medical Status Codes

ΡĪ

PD Cause: 4038 Could Not Duplicate Concern Fired when closing

Concern: 1008 Fired on Bolt Closing

Unknown

C

12/22/10 Per call from Knapik, he was in the deer stand, loaded his rifle, safety was off and it fired when closing the bolt. He has made no alterations to the rifle.cm

Firearm Information

Mfg. SKU Type Model/Ga. Serial Bbl. DOM Remington CF/BA 700 /270 WSM n/a G6543929 XZ 12/28/2005 5:54:13 AM

Date Purchased Where Purchased **Original Owner** Accessories

AMERICAN ROD & GUN

Y

CONCERN: FBC

Ammunition Information

UPC Mfg. Cal./Ga. SKU DOM Mfg. Code Type Winchester /130Concern Other **Factory** Reload 0: Silvertip Y N

Other Products Information - None Defined

Settlement

Remington /700 /CF/BA

Cash Reim. Cash Settlement Release of Claims Release Date Reimbursement Date Date Settlement APV APV

Replace TPA, clean, test fire at no charge to restore confidence

> Repair/Replacement Repair/Replacement Cost Date

47.40 4/19/2011

12/22/10 Mailing ARS.cm 4/7/11 Knapik called for update. Repair not logged in for PS. Emailed Pence to have Prod Serv inspect ASAP.cm 4/15/11 Per Ilion, could not duplicate customer concern replace TPA, clean, test fire at 1/2 normal cost to restore confidence.cm 4/19/11 Knapik called on 4/18 and left message that he will not pay, Remington should be taking care of. If he gets it back unrepaired and something happens it will be on us. Replace TPA, clean, test fire at no charge to restore confidence. Left voice message that we could not duplicate but I would have them replace TPA no charge to restore faith in rifle.cm

Examination[Remington /CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		4/8/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		24" 270 WSM
	Date Code		XZ
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	- · ·
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.012
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
Trigger	Pull	Select	3.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

5489

NOTE: Please complete and print this form, and then include it with your firearm.

	2	4	1
¥	Z	14	10
		30	5
	į	01	7

Nodel Number: 700 270 WSM	Serial Number: 66543 929		
Are you the original owner?: YES NO			
Name: Michael Kngiko	Date of Purchase:		
	lverk Rold		
city: L2 Grange	State: 1X Zip: 75915		
Phone (Daytime): (572)949 - 4270	Fax:		
E-mail Address: (if e-mail address is provided, notification sent) ME Knzy K (2) U.Com	of receipt and shipment will be		
E-mail Address: I would like to receive future e-mail updates from Rer	nington.		
Please describe your problem and date of occurrence	:		
I had gon spright, Chacked to make some	there wasn't 2 billiten		
puly had about 10	rtoff, bun has rounds Lived Since		
prochesed new (2) be	290 July 290		
500 			
Ammunition Information:			
Manufacturer: Winchester	Type: Billistic Silvertip		
Other (i.e. bullet weight/type, shot size, powder):			
130 yvzin bellistic Silvertip			
Handload Information:			
Powder Used:	Powder Weight:		
Case/Huil Used:	Primer Used:		
Bullet Type/Shot Size:	Reloader Used:		
	M APR 1 5 2011		
	BY:		

Firearms Care (Cleaning and Lubrication):
Brand of cleaning solution used: Vemington
How often do you clean the bore? (Months or Number of rounds) Cleanel 2bot 41: nes
How often do you clean the action? (Months or Number of rounds) 2600+ 46incs
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: Venington oil
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds) when gtoring
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?
YES NO
When was the last time that your firearm was serviced by a Remington authorized
repairmen/gunsmith?) Nev LV
What we say



LS IN YOUR FIREARM OR IN THE SAME BOX WITH THE . . IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND ME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND

reack your tirearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)

:: Remove all accessories from your firearm to prevent loss or damage.

:: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.

Could not deplicate cust. CONCERN.
CAN offen to Replace TPA, clean +
Trest fine At 1/2 Normal cost, to
Restore confidence in rifle.

Quote

Mitchell, Christy

From:

Mitchell, Christy

Sent:

Monday, December 20, 2010 8:29 AM

To: Subject: Mitchell, Christy FW: Michael Knapik

Call Monday

Christy Mitchell

From: Fulcher, Dell Marie

Sent: Friday, December 17, 2010 5:03 PM

To: Mitchell, Christy Subject: Michael Knapik

I didn't have time to call him back.
Michael Knapik Pronounced - Cuh Nah Pic
3501 Rock Creek Rd.
LaGrange, TX 78945
Ph: 512-968-8270

His voice mail stated he had a FBC but no model number or serial number.

Thanks, ©

Dell Fulcher | Consumer Affairs Administrator/Armorer School Administrator Remington Arms Company, Inc.

870 Remington Dr., PO Box 700, Madison, NC 27025-0700

Phone: 1.800.243.9700 | Phone: 336.548.8686 | Fax: 336.548.7872 or 336.548.7883

Freedom Group Family of Companies: Remington | Marlin | Bushmaster Firearms | DPMS / Panther Arms | H&R | Barnes Bullets | Advanced Armament Corp | Mountain Khakis | EOTAC | Dakota Arms | Parker Gun

Confidentiality/Proprietary Note: This e-mail and any files transmitted with it are intended solely for the use of the individual or entity to which they are addressed. If you are not the intended recipient or the person responsible for delivering the e-mail to the intended recipient, be advised that you have received this e-mail in error and that any use, dissemination, forwarding, printing or copying of this e-mail is strictly prohibited. If you have received this e-mail in error, please reply back to sender advising that you have received the e-mail in error and delete this e-mail from your system.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	12/22/2010 REQUESTED BY:	christy
QUANTITY:	1 WEIGHT PER PACKAG	E: 10
PLEASE CHECK ONE:		
MEDIA		XX
COORDINATOR		
TO MAIL	I WILL MAIL	
DESCRIPTION:		
	700	

LABEL INFORMATION

MAIL LABEL TO:	Michael Knapik 3501 Rocky Creek Rd LaGrange, TX 78945
RETURN ITEM TO	: Rem Prod Serv

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

```
4XX596 DEC 23, 2010 ALL CURR USD 1 OF 1 SVC GNDCOM ACT HT 10.0 LBS
TRACKING# 1Z4XX5969065481424
REF 1:MICHAEL KNAPIK/CD/CM
REF 2:700

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHG 10.59 PUB+HANDLING 10.59
```







