Remington Arms Co., Inc. Product Service Legal Case #:6093

Case Information

**Incident Date** Obsolete RE# **Date Opened** Date Opened(PS) **Date Closed** Pre Lit Lit 225582 3/11/2011 4/8/2011 4/8/2011

Customer Information

Street City Contact **Business** First Name Last Name State Zip Age Type Mihalak's Guns 9263 Crane Rd. Cranesville PA 16410 W 814-756-4092 Reporter Mihalak's Guns

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Altered Adjustments or Components Cause:4006

Unknown

S Concern:1007 Fired on Safe Release

C FSR

Dealer sent rifle in with our Factory Repair Form. Dealer said that consumer stated the rifle fired when he took safety off. Consumer stated he did not have finger on trigger. Dealer stated to inspect & repair firearm. df

Firearm Information

Mfg. Remington

Type CF/BA Model/Ga.

SKU 26031

Serial E6563225

Bbl. DOM 6/9/1999

PT

**Date Purchased** 

Where Purchased

700/2506 REM Accessories

**Original Owner** 

ACUSPORT CORPORATION

U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims

Release Date

Reimbursement

Cash Settlement

Cash Reim. Date

Date APV APV

Per Ilion - Quote to repair

Repair/Replacement

Repair/Replacement Date

4/19/11: Per Ilion - TA set screws altered. Trigger will not return properly. Replace TA, clean & test fire at 1/2 normal cost quote. Left msg for dealer to call me concerning report & quote. Dealer called & apprvd quote. Paid by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
Examination	Examiner		B.TRAVIS	
	Exam Date		4/8/2011	
	Product Type		RF	
	Action Type		A	
	Assigned To		T.NAGLE	
Cause	4006	Altered Adjustments or Components		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6093&Type=Case

4/19/2011

	Description		24" 2506 REM
Barrel	Date Code		PT
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed	d	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receive	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	.014
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
	Pull	Select	2.5"
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

MIHALAK'S GUNS 9263 Crane Road Cranesville, PA 16410 (814) 756-4092

Model:




24" PT6/99 2,5"

## Remington

161		
Factor (NOTE: Please print and comp	y Repair Instructions lete this form, and then include it with your firearm.)	
Model Number: 700 BDL EMB. I	REC. Serial Number: E6563225	
Are you the original owner?:	NO	
Name: BARRY REISER	Date of Purchase: $U \mathcal{N} \mathcal{K}$ .	
Address (no PO Boxes):		
	State: Tin.	-
City;	State. Zip:	<u>'</u>
Phone (Daytime):	Fax:	4 -
E-mail Address:  I would like to receive future e-mail upd	ates from Remington.	·
Please describe your problem:		7
CUSTOMER STATE	D FIREHROM (FIRED) WHEN HE	1
[N3/090C 3/11/12	D / /Kerrice ( ( / rees) volide //B	1
THE FAME OF	FF. HE DID NOT HAVE	-
TOOK SAPETY OF	F. HE DID NOT HAVE	4
= 13650 011 =0	District All Charter	4
FINGER ON TRI	GGER. PLUAVE INSPECT &	4
		ŧ.
REPAIR FIREHR	M. THOMAS J. MIHACALG	
Ammunition Information:		
Manufacturer:	Type: The Myalac	7
Other (i.e. bullet weight/type, shot size, power	der):	Ω ≤
	1	926 98
	and the second s	HALA 263 ( nesviii (814)
3225 AV	Powder Weight:	75 e a
	Primer Used:	- 46 A C
700	Reloader Used:	164 192
MIN MONO HAND HAND BRIDG SHAD (MIN HAN) HAN	Reloader Osed:	- 15g RS
		<b>-</b>
-WUZZ336Z	of rounds)	
How often do you clean the action? (Months of	or Number of rounds)	
How often do you clean the trigger assembly	? (Months or Number of rounds)	ZZZVE
		9 - 2044
Brand of lubricant used:	API	1 5 2011

MIHALAK'S GUNS 9263 Crane Road Cranesville, PA 16410 (814) 756-4092 BY: ....



	· · ·				igns as		
How ofter	n do you lubri	cate the bore? (M	lonths or Num	ber of round	s)		
How ofter	n do you lubri	cate the action? (	(Months or Nu	mber of roun	ds)	Į.	
How ofter	do you lubri	cate the trigger a	ssembly? (Mo	nths or Num	ber of rounds)		
Have you YES		cleaning and ma	intenance rec	ommendation	ns on our web site o	or in our owner	s manual?
Comment	s:					,	
		4 4 4					
When was	s the last tim	e that your firear	m was service	d by a Remir	gton authorized rep	pairman/gunsm	ith?
What wer	e the service	s performed?					
		· · · · · · · · · · · · · · · · · · ·					
			*	9 ·			

Ship your INSURED firearm by either UPS or Parcel Post to:

## **REMINGTON ARMS CO., INC**

ATTN: Arms Service Divison 14 Hoefler Ave Ilion, NY 13357

**WARNING:** DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. **THIS IS A VIOLATION OF FEDERAL LAW.** IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm before sending it.
- : Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

T.A. set screws Altered. Trig. will not between properly. replace TPA, clean+ Tist fineAt 1/2 normal cost.

MITALAN'S STOM
9069 Dame Florid
Grand M. Proposition
181 & 185 Alloh

Quote

