E edna.villarreal@ymail.com

Remington Arms Co., Inc.
Product Service
Legal Case #:6099

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

229585 4/25/2011 4/8/2011 4/26/2011

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Reporter Edna Villarreal C 361-527-5981

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

411 N. Maria St Hebbronville TX 78361

PΙ

Incident

PD Cause: 4038 Could Not Duplicate Concern

Villarreal

Unknown

S Fired on safe release Concern:1007 Fired on Safe Release

Alfonso

 \mathbf{C}

4/8/11 Per call from Edna, her husband has a Model 700 that has twice fired when the safety was released.cm

World To our non-gama, not indoduce the different vocality and the different value of the d

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/17 REM
 n/a
 6546886
 CW
 4/1/1972

Date Purchased Where Purchased Accessories Original Owner

TWO PIECE BASE U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Reimbursement Release Date Reimbursement Release Date APV APV

Per Ilion, replace TPA, clean, test fire at BLSM program price

Repair/Replacement Cost Repair/Replacement Date

30.40 4/28/2011

4/8/11 Emailing ARS, letter and repair form.cm 4/28/11 Per Ilion, could not duplicate concern. Trigger assm dirty, set screws altered. Replace TPA, clean, test fire at BLSM program price of \$20 + S&H.cm

Examination[Remington/CF/BA]

 Part
 Sub-Part
 Code
 Comment

 Examiner
 B.TRAVIS

 Exam Date
 4/26/2011

 Product Type
 RF

 Action Type
 A

 Assigned To
 T.NAGLE

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6099&Type=Case

4/28/2011

Cause	4038	Could Not Duplicate Concern	
<u> </u>	Description		24" 17 REM
Barrel	Date Code		CW
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed	<u>-</u>	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.007
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1000	False	
	Condition	Slightly Worn; Functioning	DIRTY,TRIG NOT RETURNING PROPERLY
Trigger	Pull	Select	2#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6099&Type=Case

4/28/2011

Non-Remington Components	Description		TWO PIECE BASE		

24" CW4/72 2#

6099

April 8, 2011

Alfonso Villarreal 411 N Maria St Hebbronville, TX 78361

Subject: #6099, Model 700

Dear Mr. Villarreal,

Thank you for your patience. You should receive an email with the UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory within the next 24-48 hours. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the boxes with "Product Service".

Also, complete the repair form and insert it inside the box also.

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com DECERVED APR 2 7 2011

BY:----

6546886 Model: 700 RE00229585 could not duplimate concern. T.A. directy eset screws Altered. Replace TPA, chan & 1887 kine under BLP for 820.00+ ship

Quote

gton Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

Factory Repair Form

Model Number:	Reminston 7	Serial I	Number:	654 6886	
Are you the original owner? $\mathbb{N}_{\mathbb{C}}$					
Name: AIFonSo VIIIacreal Date of Purchase: 2003					
Address:	P.O.BAX 3	37 /411	n. ma	വദ	
City: Heb	bronville State:	TX Zip:	7831	01	
Home phone: 3615275327 Daytime phone: 3612310068					
Cell phone:	3613182226	Fax: 36	1527	3571	
City: Hebbranulik State: TX Zip: 78361 Home phone: 3615275327 Daytime phone: 3612310068 Cell phone: 361318224 Fax: 361527 3571 Email Address Eding villarrect eximal Com					
Please describe	your problem and the	date of occurrer	nce:		
Guni	Gin is going off when you take it off				
SO Patul	TIL HOS HER	nen +wi	(2 TO)	me it could	
Jane 19	hern fatal.	260 : 9011	0		
nave	Octobra 1	march 2	011		
•	·				
					
Ammunition Info	ormation: Re	mington	ammu	ni tien	
Manufacturer:	Reminstra	Туре:	25 Gr.	Horncoy AP	
Other (i.e. bullet	t weight/type, shot size	, powder):	116	RITEZ_	
					
Handload Infor					
Powder Used: Case/Hull Used	NIA	Powder wt: 「	1/6		
Case/Hull Used	A/N		Used: n		
Bullet Type/Sho			ler Used:	NIA	
Firearms Care	(Cleaning and Lubric	ation):			
Brand of cleaning	ng solution used: 💢	eminaton	Oil		
How often do yo	ou clean the bore? (Mo	nths or # of rour	ids): – ೮	,	
How often do yo	ou clean the action? (M	onths or # of rol	<u>ınds): კა</u>	Shots	
How-often-do-yo	ou clean the trigger? (M	fonths or # of ro	unds):	-ε	
Brand of lubrica	ntused: Remins	ton			
How often do you lubricate the bore? (Months or Number of rounds) - o -					
How often do you lubricate the action? (Months or Number of rounds)					
How often do you lubricate the trigger assembly? —o —					
Have you ever reviewed the cleaning and maintenance recommendations on our					
web site or in our owners manual? No					
When was the last time your firearm was serviced by an authorized repair center?					
Never					
If so, what were the services that were performed? $\sim 1c$					
* Record the serial number of your firearm before sending it. *Pack your firearm for safety and to					
prevent further damage in shipping and handling, preferably in a firearm box. (Note: original firearm boxes will not be returned.) *Remove all accessories. *Provide a return address on both the outside					
and inside of the box. *Ship it insured. Our company is not responsible for damage or loss during					
shipment, so you may elect to purhcase insurance from your carrier.					

From: Mitchell, Christy (Christy.Mitchell@remington.com)

To: edna.villarreal@ymail.com; Date: Fri, April 8, 2011 10:04:38 AM

Cc:

Subject: Villarreal, Alfonso.cm.doc

Mrs. Villarreal, please print the attached and include them inside the box with the rifle. You should receive another email within 24-48 business hours that will contain the UPS ground shipping label.

If you have any questions feel free to call or email.

Christy Mitchell Consumer Affairs Adminstrator PO Box 700 870 Remington Dr Madison, NC 27025 800-243-9700, ext 8684 Fax: 336-548-7872

christy.mitchell@remington.com

Case #	6099	Date of Call	48/11	Date of Incident		PreLit Lit	Obs	
Reporter name address contact #'s				Incident Name/Age address contact #'s	411,	N. Maria	54	
email		·		email		ronville, a, villar		1. coa
Injury Medical Treatment Alleged					\$ Q1	1-527-59	8/	
cause	Ser#	Cal	DOM 172	Orig owner?	When/W	here purchased		
Ammunition	Factory/Reload	Manuf	Caliber	Bullet type/wgt	Lot#	Additional info		
Other Product	FSR	tw	i ce	20	0 (754688	6	
		, •		·				
Notoe					·			
Notes: Customer's Request								
My actions/ offers								



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

		/					
DATE:	4/8/2011	REQUESTED BY: christy /					
QUANTITY:	1	WEIGHT PER PACKAGE: / 10					
PLEASE CHECK ONE:							
MEDIA	Email to him at:	/					
COORDINATOR	edna.villarreal@ymail.com						
TO MAIL	xxxxxxxxxxxxxxxx	I WILL MAIL /					
DESCRIPTION:							
	700	. 3 /					
1	6546886						
		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					
	LABEL INFORMATION; /						
	_, (
MAIL LADEL TO:	AIC VCII.						
MAIL LABEL TO:	Alfonso Villarreal						
	411 N. Maria St						
l	Hebbronville, TX 78361 361-527-5981						
	301-327-3901						
RETURN ITEM TO:	Pom Prod Conv						
RETURNITENTO.	. Rem Flod Selv						
		=					

PLEASE COMPLETE ALL PARTS OF THIS FOR

edna.villarreal@ymail.com

4XX596 APR 8, 2011 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 10.0 LBS TRACKINGH 1Z4XX5969065151914 REF 1:ALFONSO VILLARREAL/CD/CM REF 2:700/6546886 ANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 1.00 DC 0.00 DG 0.00 SD 0.00 AD 0.00 SD 0.00 AD 0.00 SP 0.00 SP 0.00 SP 0.00 TOT PUB CHG 11.93 PUB+HANDLING 11.93









