PrintDisplay

Page 1 of 3

Remington Arms Co., Inc.
Product Service
Legal Case #:6201

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

232142 5/23/2011 5/13/2011 5/24/2011 5/12/2011

Customer Information

Type Business First Last Name Street City State Zip Age Contact

C 410-256-6163

Incident Greg Wisniewski 9318 Seven Courts Dr Nottingham MD 21236 E

gwiz8@verizon.net

Incident Information

Claims Codes Repair Medical Medical Est. Treatment Status

ΡI

PD Cause:4038 Could Not Duplicate

G Fired on bolt Concern Unknown

closing Concern:1008 Fired on Bolt Closing

C

5/13/11 Per call from Greg, yesterday when he closed the bolt on a round it fired without him touching the trigger. It has always been hard to close the bolt since he bought it new. He has shot less than 300 rounds in it.cm

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial Bbl.
 DOM

 Remington
 CF/BA
 700/223 REM
 27491
 G6426081 EY
 10/5/2004 4:36:12 PM

 Date
 Da

Date
Purchased Where Purchased Accessories
Origina
Owner

SPORTS SOUTH TWO PIECE INC BASE

CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Reimbursement Release Date Reimbursement Release Date Date APV APV

Per Ilion, to restore

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6201&Type=Case

5/31/2011

PrintDisplay Page 2 of 3

confidence in rifle will fit new TPA at no charge

Repair/Replacement Repair/Replacement

Cost

Date

47.40

5/31/2011

5/13/11 Mailing box and ARS.cm 5/31/11 Per Ilion, could not duplicate concern. Will repair hard bolt closing and to restore confidence in rifle will fit new TPA at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		5/24/2011
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		26" 223 REM HB
	Date Code		EY
	Bore Plugged	False	
 Barrel	Bulged	False	
Barrer	Fired	False	
	Fired while Obstructed]	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6201&Type=Case

5/31/2011

	Stock Condition	Slightly Worn; Functioning	ĺ
Overall	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver		False	
	Bulged	Faise]
Safety	Description	M/700 SAFETY	
	Function	Like new; Functioning	
	Sub-Assembly	ISS	
Sear	Lift	Select	.012
	Notch	Like new; Functioning	
	T4-	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Remington

26" EY100" 4.5"

6201

May 13, 2011

Greg Wisniewski 9318 Seven Courts Dr Nottingham, MD 21236

Subject: #6201

Dear Mr. Wisniewski,

Thank you for your patience. Enclosed is the UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure firearm is logged in correctly.

I apologize for the inconvenience and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

G6426081 Model: 700 RE00232142 could not duplicate conceRN.

Will Repair hand bolt closing +
TO restore confidence in Rifle

will fit new TPA At N/c

#230145

DECELVED MAY 3 1 2011

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

	
Model Number: 700 VSL	Serial Number: G 6426081
Are you the original owner?: X YES NO	
Name: Greg Wisniewski	Date of Purchase: On record
Address (no PO Boxes): 9318 Seven	CTS. Dr
city: Notting ham	State: MD Zip: 21236
Phone (Daytime): 410 256 6163	Fax:
E-mail Address:(if e-mail address is provided, notification	
sent) GWIZ80 Verizon . Det E-mail Address:	
	minetan
I would like to receive future e-mail updates from Re	
Please describe your problem and date of occurrence	
1 ±	carm for Several Years,
But because it was so Dig	, .
I seldomly Shotit, most	Likely less then 150 founds
though it as it hart my ha	and to secure the boltdown, 18/ I Purchased 4 different
in the 219 Thurs of 1	the prob was Ammo related
I I was not uchila Tiling	TO GLACO THE HALT WI KOM.
I a cos TT a Wast off	MY PINGER INAS NO WHERE HEAR
a Lemon since I bought le	The state of the s
500 characters left	
Ammunition Information: Used	Winchester White Box -
	1
Other (i.e. bullet weight/type, shot size, powder):	HTYPE Federal Premium 5+559+ bullets
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	5/13/2011 RE	QUESTED BY:	christy
QUANTITY:	1 WI	EIGHT PER PACKAGE:	10
PLEASE CHECK ONE:			
MEDIA			
COORDINATOR			XXX
TO MAIL	I <i>V</i>	VILL MAIL	
DESCRIPTION:			
[700		
G6426081			

LABEL INFORMATION

MAIL LABEL TO: Greg Wisniewski
9318 Seven Courts Dr
Nottingham, MD 21236
410-256-6163

RETURN ITEM TO: Rem Prod Serv
Case # 6201

PLEASE COMPLETE ALL PARTS OF THIS FORM, AND SEND TO THE MEDIA COORDINATOR

MAY 13, 2011 ALL CURR USD ACT WT 10.0 LBS 1 OF 1 4XX596 SVC GNDCOM ACT UT TRACKING# 124XX5969066514637 REF 1:GREG WISNIEWSKI/CD/CM REF 2:700/G6426081 HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: RS 0.50 DV 0.00 DC 0.00 COD 0.00 SD 0.00 DGD 0.00 PR 0.00 SP 0.00 AH 0.00 PUB+HANDL ING 8.08 TOT PUB CHG 8.08







