

Remington Arms Co., Inc.
Product Service
Legal Case #:6175

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
230591	5/5/2011	5/6/2011	5/6/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Charlie's Sporting Goods, Inc		Charlie's Sport	8908 Manual NE	Albuquerque	NM	87112		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	Fired when safety was released	Concern:1007	Fired on Safe Release	Unknown
C				

5/19/11 Per note with rifle, repair or replace as needed. Gun misfired twice when the safety was taken off.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	710/300 WIN MA	27414	71352489	LB	2/1/2007 7:51:33 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAL-MART STORE 1063		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/710/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, to restore confidence will replace TPA, clean, test fire at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	41.88	5/19/2011				

5/19/11 Per Ilion, could not duplicate concern. To restore confidence in rifle will replace TPA, clean and test fire at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		5/6/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 300 WIN MAG
	Date Code		LB
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/710 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	CLEAN
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	Other Remington	

Charlie's Sporting Goods, Inc.

8908 Manual NE

Albuquerque NM 87112

6175

24"
LBZ/6,
4#
Work Order

Date	W.O. No.
4/27/2011	

Name / Address
REMINGTON

Ship To

P.O. No.	Project
155641/HURTADO	

Item	Description	Ordered
	Remington M710 .300WM SN# 71352489. Please repair or replace as needed. Gun miss fired twice when the safety was taken off. could not duplicate concern. To restore confidence in rifle will replace TOP, chamber & rest Rifle at N/C. #25045	1 14.88 27 <u>41.88</u>

71352489

Model: 710



RE00230591

RECEIVED
MAY 12 2011

BY:.....







