

Remington Arms Co., Inc.
Product Service
Legal Case #:6623

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
241883	9/27/2011	9/28/2011	9/28/2011				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Richard	Barber	2601 SR 11B	North Bangor	NY	12966		H n/a

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4013 Broken or Missing Parts		Unknown	
S	Concern:1007 Fired on Safe Release			
C FSR				

Customer sent gun in with our repair form. He stated the gun would fire on safe release. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	ML/BA	700/50 CAL	27580	ML095150	DR	9/29/1997
Date Purchased	Where Purchased	Accessories	Original Owner			
	JERRYS SPORT CENTER INC	AFT MKT FIR PIN AND NIPPLE	Y			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/ML/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Repair @ n/c						

Repair/Replacement Cost	Repair/Replacement Date
\$35.26	10/10/2011

10/10/11: Per Ilion - TA very dirty. Connector is broken. Replace TA & clean & n/c. df

Examination[Remington/ML/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/28/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4013	Broken or Missing Parts	
	Description		24" 50 CAL SS

Barrel	Date Code		DR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	AFT MKT
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	ACTION DIRTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	CONNECTOR BROKEN
	Pull	---Select---	N/A
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		AFT MKT FIR PIN AND NIPPLE

16623

241
DR9/9

Remington.

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700 ML		Serial Number: ML 095150	
Are you the original owner?: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Name: Richard Barbet		Date of Purchase: Not sure	
Address (no PO Boxes): 2601 ST. Rd. 11B			
City: Bangor		State: N. Y.	Zip: 12966
Phone (Daytime):		Fax:	
E-mail Address: <input type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem: gun Fired when I Take off SaFTY.			
T.A. very dirty. CONNECTION IS BROKEN. Replace TPAT CLEAN AT N/C #250145			
Ammunition Information:			
Manufacturer: Rem + others		Type:	
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used: Triple 7 + white HOT		Powder Weight: 100 Gr	
Case/Hull Used:		Primer Used: Rem + Winchester	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			
Brand of cleaning solution used: Hopp			
How often do you clean the bore? (Months or Number of rounds) after shooting			
How often do you clean the action? (Months or Number of rounds)			
How often do you clean the trigger assembly? (Months or Number of rounds)			
Brand of lubricant used:			

OCT 04 2011

BY:

How often do you lubricate the bore? (Months or Number of rounds)	<i>after cleaning</i>
How often do you lubricate the action? (Months or Number of rounds)	<i>11</i>
How often do you lubricate the trigger assembly? (Months or Number of rounds)	<i>11</i>
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Comments:	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?	
What were the services performed?	
Ship your INSURED firearm by either UPS or Parcel Post to:	



Richard Barber
2601 State Route 11B
North Bangor, NY 12966

*gun fails to Cock, and
When it does it Will
fire by taking off the
safty.*

Richard

REMS CO., INC

Service Division
er Ave
13357

OUR FIREARM OR IN THE SAME BOX WITH THE
YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE
ADDRESS (WITH ZIP CODE), TELEPHONE AND

e in shipping and handling. Preferably,
turned.)
or damage.
e box. Shipments without a proper

Remington is not responsible for
damage or loss during shipment, so you may elect to purchase insurance from your carrier.

delines:

med to you C.O.D. (To avoid C.O.D. Charges, please
h. your gun)

estimate detailing the nature of the repair, applicable taxes
air estimate. Repairs can be paid by check, money order,
or VISA). If you wish, you can expedite repairs over
billed to your credit card.

ML095150
Model: 700ML



RE00241883







