Remington Arms Co., Inc. Product Service Legal Case #:7086

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 252493 1/4/2012 12/14/2011 1/5/2012

Customer Information

Type **Business** First Name Last Name Street City State Zip Age Contact Bullets & Bows Bullets & Bows 110 W. Louisiana Ave. W 337-334-0033 Reporter Kenny Raine 70578 LA

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4038 Could Not Duplicate Concern

S Concern:1007 Fired on Safe Release

Unknown

C FSR

12/14/11: Dealer called in. He stated a consumer brought him the gun & said he had a FSR with it. No report of injury or damage. df

Firearm Information

Mfg. Model/Ga. SKU Bbl. DOM Type Serial Remington CF/BA 700/7MM REM MA 27480 E6842148 WP 8/11/1995 **Date Purchased** Where Purchased Accessories **Original Owner**

WAL MART WAREHOUSE 3R TWO PIECE BASE U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date Settlement APV APV

Per Ilion - Quote to repair

Repair/Replacement Repair/Replacement
Cost Date

12/15/11: Mailing ARS & forms. df 1/4/12: Per Ilion - Could not duplicate concern. TA very dirty. Can offer to replace TA, clean & test fire @ 1/2 normal cost - quote. df


Examination[Remington/CF/BA]

Part Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		1/5/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7MM REM MAG
	Date Code		WP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7086&Type=Case

1/23/2012

l	Shroud	Slightly Worn; Functioning	
Bolt			
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	•
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.013
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	VERY DIRTY
	Pull	Select	5.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE



7086

December 14, 2011

Bullets & Bows Attn: Kenny

110 W. Louisiana Ave.

Raine, LA 70578 Phone: 337-334-0033

Ref: #7086, Model 700, Serial # E6842148

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

E6842148

Model: 700

RE00252493

could not duplicate concepts

T. A. wany Linty, che not fin

to up how TOA, che no Lest

One of the normal cost.

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number Serial Number / Description SR00006750

E6842148

Model 700 Center Fire Customer:

BULLETS & BOWS ATTN: KENNY 110 W. LOUISIANA AVE.

RAINE, LA 70578 US

Date of Request: 12/15/2011

Printed: 12/15/2011

Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Product Service # 7086 - FSR

Parts And Service Details

Material

Type

Description

Qty Needed Warranty

Price

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00

.00

Print		Reset
-------	--	-------

Model Number: 200	Serial Number: E 68 42148		
Are you the original ow		I NO	
Name:	Date of Purchase:		
Address (no PO Boxes):			
City:	State:	Zip:	
Phone (Daytime):	Fax:		
E-mail Address:(if e-mail address is provid be sent)	ed, notification of	receipt and shipment will	
E-mail A □ I would like to receive future e		m Remington.	
Please describe your problem and date of occurrence:			
		·	
·			
		· ·	
		:	
:		<u> </u>	
500 cha	racters left		
Ammunition I	nformation:		
Manufacturer:	Type:		
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used:	Powder Weig	ght:	
Case/Hull Used:	Primer Used:		
Bullet Type/Shot Size:	Reloader Us	ed:	
Firearms Care (Cleaning and Lubrication):			

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >□ YES □ NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
 □ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling.
Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

ARS LABEL REQUEST FORM

DATE:	12/15/2011	Service Request #	SR00006750
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

BULLETS & BOWS ATTN: KENNY 110 W. LOUISIANA AVE. SR00006750 RAINE, LA 70578 US Email:

RETURN ITEM TO:

ILN

Arms Services





4XX596 DEC 15, 2011 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS TRACKING# 1Z4XX5969066834149 ALL CURRENCY USD REF 1:SR00006750 REF 2:

HANDLING CHARGE 0.00 FRT: 3R0

SHIPMENT PUB RATE CHARGES: SVC T/P USD

DV 0.00 COD 0.00 RS 0.50

DC 0.00 DGD 0.00

AH 0.00 PR 0.00 ROD 0.00

TOT PUB CHG 10.27 PUB+HANDLING 10.27

