Remington Arms Co., Inc. Product Service Legal Case #:6483

Case Information

RE# Date Opened(PS) **Date Closed Incident Date** Obsolete **Date Opened** Pre Lit Lit 8/22/2011 12/7/2011 12/6/2011 249312 X

Customer Information

Last Name Business First Name Street City State Zip Contact Type Age C 276-806-7172 Wayne 31 Family Dr. Butcher Cana VA Incident 24317 E rbutcher@hughes.net

Incident Information

Medical Status Codes Repair Est. **Medical Treatment** Claims

PΙ

PD Cause: 4013 Broken or Missing Parts S Concern:1028 Fired With Safe ON

Unknown

C Fired with safety on

8/22/11: Customer called in. He stated that about a month ago his muzzleloader fired with the safety on. He's not sure if there is a broken part inside & wants to have it checked out. No damage, No injury. df

Firearm Information

Mfg. Remington

Type ML/BA

Model/Ga. 700ML/50 CAL

SKU 27572

Bbl. Serial ML110766 RR

DOM 11/11/1997

Date Purchased

Where Purchased ACUSPORT CORPORATION

Accessories TWO PIECE BASE Original Owner N

CONCERN:FSO

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700ML/ML/BA

Settlement Release of Claims Release Date Reimbursement

Cash Settlement

Reim. Date APV

Cash Date APV

Per Ilion - Repair (a)

n/c

Repair/Replacement Repair/Replacement Cost Date \$35.40 12/18/2011

8/22/11: Mailing ARS, letter, form. df 12/18/11: Per Ilion - Safety not functioning. Replace TA, clean & check over at n/c. df

Examination[Remington/ML/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		12/7/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4013	Broken or Missing Parts	SAFETY NOT FUNCTIONING. SAFETY CAM BROKEN OFF
Barrel	Description		24" 50 CAL
	Date Code		RR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	i irea withe Obstructed	1	7

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6483&Type=Case

12/18/2011

	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Select	AFT MKT
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Select	
	Handle	Slightly Worn; Functioning	
	Stop	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Abused; Not Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	lesis	False	
Trigger	Condition	Slightly Worn; Not Functioning	SAFETY NOT FUNCTIONING WILL FOS
	Pull	Select	4#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

Remington



6483

August 22, 2011

Wayne Butcher 31 Family Dr. Cana, VA 24317 Phone: 276-806-7172

Ref: #6483, Model 700ML

Dear Mr. Butcher,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and a form.

Please include a copy of this letter and form to put inside the shipping container. The letter and form inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC
Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872



SAFETY NOT Functioning.

Replace TPA, clean+cleckouen

AT 14/c

230145 DEC 1 3 2011

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com Print

Model	Serial						
Number: 700 M/	Number: ML/10766						
Are you the original owner?: ☐ YES XNO							
Name: / 1	Date of Purchase:						
Wayne Butcher	7/16 11						
Address (no PO Boxes):							
31 Family Dr							
City: Cana	State: UA Zip: 24317						
Phone (Daytime): 276-806-7172	Fax:						
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent)							
E-mail A							
	e-mail updates from Remington.						
I have not fired put a primer.	nced the safety does into function						
500 cha	racters left						
Ammunition I	nformation:						
Manufacturer:	Type:						
Other (i.e. bullet weight/type, shot size, powder):							
Handload In	distribution and the state of t						
Powder Used:	Powder Weight:						
Case/Hull Used:	Primer Used:						
Bullet Type/Shot Size:	Reloader Used:						
Firearms Care (Cleaning and Lubrication):							

Brand of cleaning solution used:					
How often do you clean the bore? (Months or Number of rounds)					
How often do you clean the action? (Months or Number of rounds)					
How often do you clean the trigger assembly? (Months or Number of rounds)					
Brand of lubricant used:					
How often do you lubricate the bore? (Months or Number of rounds)					
How often do you lubricate the action? (Months or Number of rounds)					
How often do you lubricate the trigger assembly? (Months or Number of rounds)					
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >□ YES □ NO					
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)					
What were the services performed?)					
Ship your INSURED firearm by either UPS or Parcel Post to:					
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357					
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.					
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper					

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		8/22/2011	REQUESTED BY:	Dell
QUANTITY:	1		WEIGHT PER PKG:	10 lbs
PLEASE CHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXX
DESCRIPTION:	Ref# 6483 rifle			

LABEL INFORMATION

MAIL LABEL TO: Wayne Butcher

31 Family Dr. Cana, VA 24317 Phone: 276-806-7172

RETURN ITEM TC Remington Arms

Attn: Product Service

Ilion, NY

PUBASE COMPUBIEAUL PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

4XX596 AUG 22, 2011 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 10.0 LBS
TRACKING# 1Z4XX5969067030407
REF 1:WAYNE BUTCHER/CD/DMF
REF 2:REF#6483/RIFLE
HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD

DV 0.00 COD 0.00 RS 0.50
DC 0.00 DGD 0.00 SD 0.00
HH 0.00 PR 0.00 SP 0.00
TOT PUB CHG 9.08 PUB+HANDLING 9.08







