Remington Arms Co., Inc. Product Service Legal Case #:6478

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed** Incident Date Pre Lit Lit Obsolete 237952 8/15/2011 8/22/2011 8/22/2011

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact W 970-596-4440 John L Cosentino 805 West Tomichi Ave Gunnison CO 81230

E johncosentino@gunnison.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PI PD

Fired when loading rounds in

Cause:4038 Could Not Duplicate Concern

S chamber Concern:1008 Fired on Bolt Closing

Unknown

8/29/11 Per letter with rifle, this rifle has discharged unexpectedly in the following situations: 1. while loading the rounds into the chamber with the safety on; 2. With the safety on and a round in the chamber and moving it from his shoulder to the front of his body; 3. With the safety on and a round in the chamber placing the rifle into an upright stand.cm

Firearm Information

Mfg. Remington Type

Model/Ga.

SKU

Serial Bbl. DOM

CF/BA

700/7MM REM MA

25803

C6586512 WK 8/21/1990

Date Purchased

Where Purchased

Accessories

Original Owner U

ARKANSAS IMPORT & DISTRIB. CO. SCOPE, RINGS, BASE, SLING CONCERN: UNEXPECTED DISCHARGES

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Release of Claims Settlement

Release Date

Reimbursement

Cash Settlement

Reim. Date Cash APV Date APV

Replace with new 700 BDL

Repair/Replacement Cost Repair/Replacement Date

301.00

9/6/2011

8/29/11 Per Ilion, could not duplicate concern. Trigger assm dirty and rusty. Replace TPA, clean, test fire at 1/2 normal cost.cm 9/6/11 Repair has been notated that the rifle was scrapped. Emailed Pence and he said that Anne Harper said she was refunding. Spoke with Cosentino and he said that Ben told him we would take care of when it came in and replace it. The rifle has been scrapped therefore I requested that Ilion order a new 700 BDL for Cosentino.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/22/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7MM REM MAG
	Date Code		WK
	Bore Plugged	False	
	Bulged	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6478&Type=Case

9/6/2011

	Fired	[Feles	 i
		False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,RUSTY
	Pull	Select	5.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE,RINGS,BASE,SLING

Mitchell, Christy

From:

King, Janice

Sent:

Tuesday, September 06, 2011 11:21 AM

To:

Mitchell, Christy

Subject:

RE: John L. Cosentino - PS # 6478

No record in SAP of sending him a check

From: Mitchell, Christy

Sent: Tuesday, September 06, 2011 11:00 AM

To: King, Janice

Subject: FW: John L. Cosentino - PS # 6478

Janice, I'm going to replace Cosentino's gun but wanted to be sure there was not a refund out there in his name also. I've received conflicting info so wanted to double check.

John Cosentino 805 West Tomichi Ave Gunnison, CO 81230

I don't have an amount for you but I would guess it would be in the \$500-800 range.

Christy Mitchell

From: Harper, Anne M

Sent: Tuesday, September 06, 2011 9:43 AM

To: Mitchell, Christy

Subject: RE: John L. Cosentino - PS # 6478

Doesn't look like any of us did. We wouldn't though since it's a Product Service repair. I have no idea why Ron Pence would think I was refunding. I haven't touched this one looks like.

From: Mitchell, Christy

Sent: Tuesday, September 06, 2011 9:40 AM

To: Harper, Anne M

Subject: RE: John L. Cosentino - PS # 6478

237952. He just called and I need to know if a refund is in progress and get some of the paperwork for my file. Did anyone call him about the refund?

Christy Mitchell

From: Harper, Anne M

Sent: Tuesday, September 06, 2011 9:39 AM

To: Mitchell, Christy

Subject: RE: John L. Cosentino - PS # 6478

Do you have a repair number?

From: Mitchell, Christy

Sent: Friday, September 02, 2011 3:51 PM

To: Harper, Anne M

Subject: FW: John L. Cosentino - PS # 6478

Importance: High

Just checking with you on this one. Ron Pence scrapped the original gun and said you were refunding. There are no notes on the repair in history or notes from you so I wanted to see where this was at since it's a PS repair. I need to document my file on him.

Christy Mitchell

From: Fulcher, Dell Marie

Sent: Friday, September 02, 2011 11:13 AM

To: Mitchell, Christy

Subject: John L. Cosentino - PS # 6478

Importance: High

Happy Friday!

This gentleman called & wants a call back concerning the quote the factory mailed to him. The voice mail said that he had a different understanding of what was going to be done to take care of him. He said he was an attorney.

Phone: 970-596-4440

Just a FYI - I had a case this morning where the guy got his quote & my phone call & called me - demanded that we fix his rifle at n/c.

Per Danny E. on that one - I can reduce his quote to \$37 but beyond that - we will have to consult with legal counsel. When we spoke with Lauren - she said that we shouldn't do anything that could affect current litigation. Whatever that means....

:)

Dell Fulcher | Consumer Affairs Administrator/Armorer School Administrator Remington Arms Company, LLC

870 Remington Dr., PO Box 700, Madison, NC 27025-0700

Phone: 1.800.243.9700 | Phone: 336.548.8686 | Fax: 336.548.7872 or 336.548.7883 | Email:

dell.fulcher@remington.com

Freedom Group Family of Companies: Remington | Marlin | Bushmaster Firearms | DPMS / Panther Arms | H&R | Barnes Bullets | Advanced Armament Corp | Mountain Khakis | EOTAC | Dakota Arms | Parker Gun

Confidentiality/Proprietary Note: This e-mail and any files transmitted with it are intended solely for the use of the individual or entity to which they are addressed. If you are not the intended recipient or the person responsible for delivering the e-mail to the intended recipient, be advised that you have received this e-mail in error and that any use, dissemination, forwarding, printing or copying of this e-mail is strictly prohibited. If you have received this e-mail in error, please reply back to sender advising that you have received the e-mail in error and delete this e-mail from your system.

24" WK 8/90 S.5

JOHN L. COSENTINO

Attorney At Law

Member, Colorado, Massachusetts, Rhode Island Bar

805 West Tomichi Avenue Gunnison, Colorado 81230

Telephone 970-596-4440

Fax 970-641-5528/ Email: johncosentino@gunnison.com

August 9, 2011

596-4440

REMINGTON

Ilion Firearms Plant & Custom Shop 14 Hoefler Avenue Ilion, NY 13357

Re: Remington 700 Serial # C6586512 護C6586512 Model: 700



Gentlemen,

After speaking with customer service on today's date enclose please find my 700 with Burris scope inside my black hard plastic rifle travel case.

I explained to Ben that the rifle has discharged unexpectedly in the following situations:

- 1. While loading the rounds into the chamber with the safety on;
- 2. With the safety on and a round in the chamber and moving it from my shoulder to the front of my body; lastly,
- 3. With the safety on and a round in the chamber placing the rifle into an upright stand.

The gentleman in customer service advised me that whatever it takes to repair the problem including the replacement of parts/trigger mechanism will be done to right the situation.

As an aside, I am a former Special Forces Green Beret so I am somewhat weapon savvy.

Thanking you in advance, I am

Verw Truly,

John L. Cosentino

AUG 2 6 2011

BY:

could not duplicate concern T. A. dinty + Rusty. heplace TPA, clean + Test fine at //z Nonmal cost





