Remington Arms Co., Inc. Product Service Legal Case #:6560

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed** Incident Date Pre Lit Lit Obsolete 242769 10/7/2011 9/13/2011 10/10/2011

Customer Information

Type **Business** First Name Last Name Street City State Zip Contact Age PO Box 9 H 318-567-2691 Incident Charles Ford Converse LA 71419 20912 Hwy 174 E ford5719@bellsouth.net

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

Cause:4038 Could Not Duplicate Concern PD Hole in roof

Fired with safety on

Concern:1028 Fired With Safe ON

Unknown

9/13/11 Per call from Ford, about 4-5 years ago, with the safety on, standing on his porch with the gun pointed up it fired when he was unloading the blind mag. He had unloaded the one in the chamber while he was still in the field.cm

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 700/30-06 SPRG

SKU 27478

Serial Bbl. DOM E6859787 DP 9/6/1995

Date Purchased

Where Purchased

Accessories

Original Owner

WAL-MART WAREHOUSE #3R TWO PIECE BASE, BOTTOM HALF RINGS

Y

CONCERN:FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement

Reim. Date Cash Date APV

APV

Per Ilion, will replace TPA, clean and test fire at no charge

Repair/Replacement

Repair/Replacement

Cost

Date

47.40 10/17/2011

9/13/11 Mailing ARS.cm 10/17/11 Per Ilion, could not duplicate concern. Trigger assm dirty and rusty. Safety arm is broken/cracked. Will replace TPA, clean and test fire at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/10/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		DP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6560&Type=Case

10/17/2011

1	<u></u>		_
		Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning]
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning]
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False]
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select]
	Exterior Condition	Slightly Wom; Functioning	SOME RUST UNDER STOCK
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description]	M/700 SAFETY
Safety	Function	Abused; Functioning	
	Sub-Assembly	Non-ISS]
	Lift	Select	.008
Sear	Notch	Slightly Worn; Functioning	
	T. 4	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY,RUSTY SAFETY ARM CRACKED
Tricon	Pull	Select	4.5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE,BOTTOM HALF RINGS

Remington_®

22" DR9/95 4.54

المستحملك على

September 13, 2011

Charles Ford PO Box 9 20912 Hwy 174 Converse, LA 71419

Subject: Case #6560, Model 700

Mr. Ford,

Thank you for your patience. Enclosed is the UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Please mark the ends of the box with "Product Service".

I apologize for the inconvenience and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684

christy.mitchell@remington.com

DECEIVED A OCT 13 2011

BY:----



could not duplicate CONCERN. T.A. dirty + Musty. Safety ARM 15 BMOKENJEMICKED. Will replace TPA, CLEAN + TEST Pine AT N/C

#230145

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

	7,
Model Number: Rem , 700	Serial Number: E6859787
Are you the original owner?: YES NO	
Name: Charles FORD 0	Date of Purchase: 1.1997
Address (no PO Boxes): 20912 H	wy. 174
city: CONVERSE	State: LA Zip: 714
Phone (Daytime): 318-567-2691	Fax:
E-mail Address:(if e-mail address is provided, notification	n of receipt and shipment will be
seni) ford 5719@ bellsou	th net
E-mail Address:	
I would like to receive future e-mail updates from Re	emington.
Please describe your problem and date of occurrence	€;
Unloading after h	unt on myback
porch. AST ejecte	d one shell chambers
another & when & a	unt on myback and done shell, chambered to sed the boit -
I + MISFIRED, NO OI	WE was injured.
But, it was deateni	ng Have Not used
Since, because I'm	scared of 11, Heard
about Recall.	
100 Sept. 100 Se	
# cherzoters left	
Ammunition Information:	Freedom and the Advantage and
Manufacturer: Remmqtm	Type: COVE LOC.
Other (i.e. bullet weight/type, shot size, powder):	
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used	Primer Used:
Bullet Type/Shot Size:	Reloader Used:

Firearms Care (Cleaning and Lubrication): NOT SINCE MISTIRE
Brand of cleaning solution used: DUTEVS
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of Jubricant used: RemoIL
How often do you fubricate the bare? (Manths or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES NO
When was the last time that your firearm was serviced by a Remington authorized
repairmen/gunemith?)
What were the services performed?)
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Illion, NY 13357
 WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	9/1:	3/2011 REQUESTED BY: christy	
QUANTITY:	1	WEIGHT PER PACKAGE:	10
PLEASE CHECKONE. MEDIA COORDINATOR TO MAIL		XXX I WILL MAIL	
DESCRIPTION: E68:	59787	700	

LABEL INFORMATION

MAIL LABEL TO: Charles Ford
PO Box 9
Converse, LA 71419
318-567-2691

RETURN ITEM TO: Rem Prod Serv
Case # 6560

PUBASE COMPUBITE AND PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

4XX596 SEP 13, 2011 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WI 10.0 LBS
TRACKING# 124XX5969065746700
REF 1:CHARLES FORD/SWP/CHRISTY
REF 2:E6859787

HANDLING CHARGE 0.00
SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50
DV 0.00 DGD 0.00 SD 0.00
AH 0.00 PR 0.00 SP 0.00
TOT PUB CHG 10.27 PUB+HANDLING 10.27







