Remington Arms Co., Inc. Product Service Legal Case #:6435

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 8/9/2011 8/22/2011 8/7/2011 238503 8/16/2011

Customer Information

Last Name Street Type Business First Name City State Zip Age Contact H716-792-4571 Donald 63 Lake Ave. NY 14716 Incident Munson Brocton E dmunson40@yahoo.com

Incident Information

Codes Repair Est. Medical Treatment **Medical Status** Claims

PΙ

PD Cause: 4038 Could Not Duplicate Concern S

Unknown Concern:1007 Fired on Safe Release

C FSR

8/9/11: Customer called in. He stated that he bought the gun used & had a FSR while using it on 8/7/11. No damage, No injury. df

Firearm Information

SKU **DOM** Mfg. Model/Ga. Serial Bbl. Type CF/BA 700/3006 SPRG 25793 E6262405 CO 4/1/1994 Remington **Date Purchased** Where Purchased Accessories

BANGERS LP

Original Owner

N

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Release of Claims Release Date Reimbursement Settlement Settlement APV APV

Per Ilion - Quote to repair

Repair/Replacement Cost Repair/Replacement Date

8/9/11: Mailing ARS, letter, form. df 8/29/11: Per Ilion - Could not duplicate concern. TA dirty, sticky, rusty parts work sluggish. Replace TA, clean & test fire @ 1/2 normal cost - quote. Left msg for cust. to call concerning quote. df 8/29/11: Customer called. He wants gun returned as received. He stated he would install an aftermkt TA. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/22/2011
	Product Type		RF
	Action Type		A
	Assigned To]	T.NAGLE
Cause	4038	Could Not Duplicate Concern	POOR MAINTENENCE
Barrel	Description		22" 3006 SPRG
	Date Code		CO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6435&Type=Case

8/29/2011

h				
Bolt	Shroud	Slightly Worn; Functioning	RUSTY	
	Face	Slightly Worn; Functioning	RUSTY	
	Handle	Slightly Worn; Functioning	·	
	Stop	Slightly Worn; Functioning	SLUGGISH	
Extractor	Condition	Slightly Worn; Functioning	RUSTY	
	Cut Condition	Slightly Worn; Functioning	RUSTY	
	Ext/Eject Test	False		
	Block Condition	Select		
Locking	Lug Condition	Slightly Worn; Functioning		
	Notch Condition	Select		
	Exterior Condition	Slightly Worn; Functioning		
Overall	Stock Condition	Slightly Worn; Functioning		
	Fore End Condition	Select		
Receiver	Condition	Slightly Worn; Functioning		
Receiver	Bulged	False		
	Description		M.700 SAFETY	
Safety	Function	Like new; Functioning		
	Sub-Assembly	Non-ISS		
Sear	Lift	Select	.012	
	Notch	Slightly Worn; Functioning		
	Tests	Test Fired	False	
Feeding Test	Tesis	False		
Trigger	Condition	Slightly Worn; Functioning	DIRTY,STICKY,RUSTY PARTS SLUGGISH	
	Pull	Select	6#	
	Altered	False		
	Sub-Assembly	M/700 Non-Bolt Lock		

COPY OF

6435

August 9, 2011

Donald Munson 63 Lake Ave. Brocton, NY 14716 Phone: 716-792-4571

Ref: #6435, Model 700, Serial #E6262405

Dear Mr. Munson,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and a form.

Please include a copy of this letter and form to put inside the shipping container. The letter and form inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

E6262405

Model: 70

RE00238503

could not duplicate concern T.A. dirty, sticky + rusty parts work sluggish. jup man TPA clean+ tost fine at 1/2

DECERVOONA (65).

BY:

Remington Arms Company, Inc. ● 870 Remington Drive ● P.O. Box 700 ● Madison, NC 27025 Phone 800-243-9700 ● www.remington.com Print

Reset

Model	Serial					
Number: 700 8 D L	Number: <i>E6262405</i>					
Are you the original owner?: 🖺 YES 🕱 NO						
Name: DONALD R MUNSON	Date of Purchase:					
Address (no PO Boxes):						
63 LAKE AVE.						
City: BROCTON	State: <i>Ny</i> Zip: 14716					
Phone	Fax:					
(Daytime): 7/6-792-457/	Tun-					
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) DMUNSON 40 @ YA HOO . Com						
E-mail A	ddress:					
🛛 I would like to receive future e	e-mail updates from Remington.					
Please describe your proble	em and date of occurrence:					
FIREARM FIRES WH	EN SAFFTY IS PUSHED					
TO THE FIRE POSITION	V. THIS WAS THE					
FIRST TIME FIREIN						
BORE WAS CLEANED I TIME BEFOR FIREING.						
500 cha	racters left					
Ammunition Information:						
Manufacturer: RELOADS	Type:					
Other (i.e. bullet weight/type, shot size, powder):						
Handload Information:						
Powder Used: 1MR 4320	Powder Weight: 50.5					
Case/Hull Used: REMINCTON	Primer Used: CCI					
Bullet Type/Shot Size: SPITZER 1306A	Reloader Used: RCBS					
Firearms Care (Cleaning and Lubrication):						

Brand of cleaning solution used: Hoppis						
How often do you clean the bore? (Months or Number of rounds)						
How often do you clean the action? (Months or Number of rounds)						
How often do you clean the trigger assembly? (Months or Number of rounds)						
Brand of lubricant used:						
How often do you lubricate the bore? (Months or Number of rounds)						
How often do you lubricate the action? (Months or Number of rounds)						
How often do you lubricate the trigger assembly? (Months or Number of rounds)						
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >⊠ YES ☒ NO						
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)						
What were the services performed?)						
Ship your INSURED firearm by either UPS or Parcel Post to:						
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357						
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.						
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper						

return address will be refused.
:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		8/9/2011	REQUESTED BY:	Dell
QUANTITY:	1		WEIGHT PER PKG:	10 lbs
PLEASE CHECK ONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref# 6435 rifle			

LABEL INFORMATION

MAIL LABEL TO: Donald Munson
63 Lake Ave.
Brocton, NY 14716
Phone: 716-792-4571

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

BLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

AUG 9, 2011 ALL CURR USD ACT WT 10.0 LBS 1 OF 1 4XX596 AUG 9, 2011 SVC GNDCOM ACT WT TRACKING# 1Z4XX5969067414887 REF 1:DONALD MUNSON/CD/DMF REF 2:REF#6435/RIFLE HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: RS 0.50 DV 0.00 DC 0.00 0.00 COD SD 0.00 DGD 0.00 SP 0.00 PR 0.00 AH 0.00 8.18 PUB+HANDLING TOT PUB CHG 8.18





