

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7150

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
257887	2/8/2012	12/27/2011	2/9/2012				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Ron	Nowacki	1220 Western Ave	Grafton	ND	58237		H 701-331-0765

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

12/27/11 Per call from Ron, he is the original owner of this 700 and about 2 seasons ago it fired on safety release twice.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	6844649	XZ	12/1/1975
Date Purchased	Where Purchased	Accessories	Original Owner			
	OUTDOOR SPTS HQ DAYTON OHIO	TWO PIECE BASE	Y			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	30.40	2/15/2012				

12/27/11 Mailing ARS.cm 2/15/12 Per Ilion, trigger assm dirty, set screws altered. Replace TPA, clean, test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/9/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
Barrel	Description		21" 3006 SPRG
	Date Code		XZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY.WILL FOLLOW DOWN
	Pull	---Select---	4.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

# Service Request

Remington Service

PO Box 700

Madison, NC 27025-0700



ATTN: Product Serv #7150

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **ENCLOSE THIS DOCUMENT WITH YOUR RETURN.**

22'  
X2 12/7  
4.5  
00

**Service Request Number**   **Serial Number / Description**  
SR00007700

**Date of Request:** 12/27/2011  
**Date Printed:** 12/27/2011

**Customer:**  
RON NOWACKI  
1220 WESTERN AVE  
GRAFTON, ND 58237 US

**Destination:**  
Arms Services  
14 Hoefler Ave  
Ilion, NY 13357 US

Email: Christy

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

**Reason For Return**  
M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

## Service Request Section

## Parts And Service Details

Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount
----------	------	-------------	------------	----------	-------	------	--------

Serial Number:

6844649

Model: 700



RE00257887

RECEIVED  
FEB 15 2012

BY:.....

T.A. dirty, set screws altered.  
Replace TPA, clean & test under  
BLP Con & 20. +  
Quote

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

**Sub Total:** .00  
**Est Sales Tax:** .00

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number:	700 BDL	Serial Number:	6844649
Are you the original owner?: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO			
Name:	Ron Nowacki	Date of Purchase:	1974
Address (no PO Boxes): 1220 Western Ave			
City:	Grafton	State:	N.D.
		Zip:	58237
Phone (Daytime):	701-331-0765	Fax:	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent)			
E-mail Address:			
<input type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence:			
IT Happened ON Two separate occasions when I went to take a round out of the chamber when I switched from SAFTY to Fire to <del>clear</del> clear the round it fired			
Also For your information I had with sighting in a number of years ago for dipple on end of barrel Gunsmith cut 1/4" off end and re crowned Also			
500 characters left GLASS Balled The Barrel. As you can see it has been			
Ammunition Information: Well taken care of I polish the stock twice before year			
Manufacturer:	Federal	Type:	Priemur BTSP
Other (i.e. bullet weight/type, shot size, powder): 165 gr.			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	

Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used: <u>Hoppes No. 9</u>	
How often do you clean the bore? (Months or Number of rounds)	<u>Before And After Hunting Season</u>
How often do you clean the action? (Months or Number of rounds)	<u>Before And After Hunting</u>
How often do you clean the trigger assembly? (Months or Number of rounds)	<u>Yearly</u>
Brand of lubricant used:	<u>Hoppes No. 9</u>
How often do you lubricate the bore? (Months or Number of rounds)	<u>Before And After Hunting</u>
How often do you lubricate the action? (Months or Number of rounds)	<u>Before And After Hunting</u>
How often do you lubricate the trigger assembly? (Months or Number of rounds)	
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? <u>Never</u>	
What were the services performed? _____	
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoeftler Avenue Iliion, NY 13367	
<p>⚠WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p> <input type="checkbox"/> Record the serial number of your firearm before sending it.  <input type="checkbox"/> Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)  <input type="checkbox"/> Remove all accessories from your firearm to prevent loss or damage.  <input type="checkbox"/> Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused. </p>	

## ARS LABEL REQUEST FORM

DATE:	12/27/2011	Service Request #	SR00007700
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchelless	email address:	Christy.Mitchell@remington.com

### Business:

Remington Service  
PO Box 700  
Madison, NC 27025-0700  
[www.Remington.com](http://www.Remington.com)

## LABEL INFORMATION

### MAIL LABEL TO:

RON NOWACKI  
1220 WESTERN AVE  
GRAFTON, ND 58237 US  
SR00007700

Email: Christy

### RETURN ITEM TO:

ILN

Arms Services



4XX696 DEC 28, 2011 ACT WT 10.0 LBS #PK 1  
SVC GND COM BL WT 10.0 LBS  
TRACKING# 1Z4XX6988067091913 ALL CURRENCY USD  
REF 1:SR00007700  
REF 2:

HANDLING CHARGE 0.00		FRT: 3RD	
SHIPMENT PUB RATE CHARGES:		SVC T/P USD	
DV 0.00	COD 0.00	RS 0.50	
DC 0.00	DGD 0.00		
AH 0.00	PR 0.00	ROD 0.00	
TOT PUB CHG 10.27		PUB+HANDLING 10.27	

ATTN: Product Serv #7150











