

Remington Arms Co., Inc.
Product Service
Legal Case #:7103

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
250723	12/16/2011	12/19/2011	12/19/2011				X

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Chad	Rowlett	334 W. University Pkwy	Jackson	TN	38305		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4013 Broken or Missing Parts		Unknown	
S	Fired on safety release	Concern:1007 Fired on Safe Release		
C				

1/16/12 Per note with rifle, on 3 separate occasions this year at the firing range the gun went off when he turned the safety off without pulling the trigger.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	ML/BA	700/50 CAL	27572	ML076318	PR	6/17/1997
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAL-MART WAREHOUSE #3R	AFT MKT NIPPLE,FIR PIN ASSM	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/ML/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, check over and clean at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	35.40	1/16/2012				

1/16/12 Per Ilion, connector is broken. Replace TPA, check over and clean at no charge.cm

Examination[Remington/ML/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/19/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4013	Broken or Missing Parts	CONNECTOR BROKEN
Barrel	Description		24" 50 CAL
	Date Code		PR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	


Bolt	Firing Pin	---Select---	AFT MKT
	Shroud	---Select---	
	Face	---Select---	
	Handle	Slightly Worn; Functioning	
	Stop	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	CONNECTOR BROKEN
	Pull	---Select---	N/A
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		AFT MKT NIPPLE,FIR PIN ASSM

On 3 seperate occasions this year at the firing range, the gun went off when I turned the safety off with out pulling the trigger. Luckily NO one was hurt. The gun has never been tampered with. The only thing I've done is change to 209 Ignition system. 24"

PR6/97

17103

Thanks,
Chad Rowlett



Serial Number:

ML076318

Model: 700ML



RE00250723

connector is Broken.

Repace TPA, check over, clean

AT A/C

#230145

RECEIVED
DEC 20 2011

BY:.....