Remington Arms Co., Inc. Product Service Legal Case #:7012

Case Information

RE#

Date Opened 12/16/2011

Date Opened(PS) 12/7/2011

Date Closed 12/19/2011

Incident Date 11/19/2011

Pre Lit Lit

Obsolete

250943

Customer Information

Type Business First Name Last Name

Street

City

State Zip Age

Contact C 414-791-3439

Incident

Lon

5665 South Meadowpark Dr

Hales Corners

53130 WI

E lswatek@wi.rr.com

Incident Information

Claims

Codes

Repair Est. Medical Treatment Medical Status

PΙ

PD

Cause: 4038 Could Not Duplicate Concern

Unknown

Concern:1007 Fired on Safe Release S

Swatek

C FSR & sometimes will not come off Safe

12/7/11: Customer called in. He stated his rifle had a FSR & it has been very hard to take the rifle off Safe. No damage, No injury. df

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl. DOM

Remington

CF/BA

700/7MM REM MA

25803

E6895120 RP 11/8/1995

Date Purchased Where Purchased

Accessories

Original Owner

JERRYS SPORT CENTER INC TWO PIECE BASE, BOTTOM HALF RINGS

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date APV

APV

Settlement Per Ilion - Quote to repair

Repair/Replacement Cost Repair/Replacement Date

12/7/11: Mailing ARS & forms. Box order# 1282240. df 12/20/11: Per Ilion - Could not duplicate concern. TA dirty. Can offer to replace TA, clean & test fire @ 1/2 normal cost - quote. df 1/11/12: Customer called & spoke to a CSR & asked to have gun returned as received. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/19/2011
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description]	24" 7MM REM MAG
	Date Code		RP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7012&Type=Case

1/13/2012

		H	
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select] .
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	Ì
	Lift	Select	.011
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY
Triana	Pull	Select	5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE, BOTTOM HALF RINGS

emington.

please consect

spelling

December 7, 2011

Lon Swapek 5665 South Meadowpark Dr Hales Corners, WI 53130 Phone: 414-791-3439

Ref: #7012, Model 700, Serial # E6895120

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

Please include a copy of this <u>letter and service request</u> to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

enclosure



Could not duplicate concern. T.A. dinty. CAN Offer to uphace TPA, clean+ Test fine a+1/2 Morunt (cost.

Qual DEC 20 2011

BY:

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Service Request

Remington Service PO Box 700

12/07/2011

12/07/2011

Date of Request:

Printed:

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

ATTN: Product Service

Date

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number | Description

SR00006040

E6895120

Model 700 Center Fire Caliber: 7

Customer: LON SWATEK

5665 SOUTH MEADOWPARK DR HALES CORNERS, WI 53130 US

Email:

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Product Service # 7012 - FSR

Parts And Service Details

Material

Type

Description

Qty Needed Warranty

Price

Disc Amount

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: Est Sales Tax: .00

.00

Print

Reset

Model	Serial				
Number: 700	Number: <i>E 689 5/20</i>				
Are you the original owner?: ☐ YES 🕱 NO					
Name: LON SWATEK	Date of Purchase:				
Address (no PO Boxes): 5665 S. MEADOW PARK Drive					
City: HALES CORNERS	State: W/ Zip: 53/30				
Phone (Daytime): 414-235-9156	Fax:				
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent)					
E-mail A					
☐ I would like to receive future e	-mail updates from Remington.				
Please describe your problem and date of occurrence: Nov. 19 th 2011 I COULD NOT GET THE SAFETY LEVER TO COME OFF OF SAFETY POSITION, TO THE					
FIRE POSITION. ALSO, THE BOLT DOES NOT MOVE EASILY, VERY DIFFICULT AT TIMES TO OPEN AND CLOSE. ALSO, THE GUN MISFIRED WHEN TAKING SAFETY OFF-NO FINGER WAS ON THE					
GUN MISFIRED WHEN THRIVE SAFE 500 cha	racters left				
Ammunition I	nformation:				
Manufacturer: REMINGTON	Type: 7mm REM MAG 175GR				
Other (i.e. bullet weight/type, shot size, Core-Loker Proposed Pro					
Handload In	formation:				
Powder Used:	Powder Weight:				
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				
Firearms Care (Cleaning and Lubrication):					

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

Brand of cleaning solution used:
I SHOOT How often do you clean the bore? (Months or Number of ONCE A YEAR, MAYBE rounds) EVERYTIME AFTER SHOOTING AT END OF DAY
How often do you clean the action? (Months or Number of rounds) SAME AS ABOVE, CNCE OR TWICE YEAR
How often do you clean the trigger assembly? (Months or Number of rounds) ONLY CLEAVED AFTER SHOOTING, HU
Brand of lubricant used: PROTEC Remium
How often do you lubricate the bore? (Months or Number of END OF DAY, rounds) MAXIMUM OF TWICE / YEAR
How often do you lubricate the action? (Months or Number of rounds) AFTER RAIN, FIREING, IF NEEDED
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >☒ YES ☐ NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) NEVER THAT I'M AWARE OF
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoeffer Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

http://www.remington.com/asp/factory_repair_form.asp

8/25/2011

ARS LABEL REQUEST FORM

DATE:	12/07/2011	Service Request #	SR00006040
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	fulcherdm	email address:	I WILL MAIL LABEL
	· · · · · · · · · · · · · · · · · · ·		

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

LON SWAPEK 5665 SOUTH MEADOWPARK DR HALES CORNERS, WI 53130 US SR00006040

Email:

RETURN ITEM TO:

ILN

Arms Services



ATTN: Product Service

4XX596 DEC 7, 2011 ACT WT 10.0 LBS #PK 1 SVC GNDCOM BL WT 10.0 LBS TRACKING# 1Z4XX5969065977765 ALL CURRENCY USD REF 1:SR00006040 REF 2:

HANDLING CHARGE 0.00 FRT: 3RD SHIPMENT PUB RATE CHARGES: SVC T/P USD RS 0.50 DV 0.00 COD 0.00 DC 0.00 DGD 0.00 AH 0.00 0.00 ROD 0.00 TOT PUB CHG 9.61 PUB + HANDLING 9.61





