rimuispiay rage 1 01 2

Remington Arms Co., Inc. Product Service Legal Case #:6522

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 240839
 9/15/2011
 8/30/2011
 9/16/2011
 8/28/2011

Customer Information

Type First Name Last Name Street City Zip Contact Business State Age 131 Rio Grande H 386-409-7282 Incident Bert Uyttewaal Edgewater FL 32141

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

S

PD Cause:4038 Could Not Duplicate Concern

Concern:1008 Fired on Bolt Closing

Unknown

C FBC

8/30/11: Customer called in. He stated that he had a FBC while shooting on 8/28/11. df

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/3006 SPRG
 n/a
 294430
 OK
 6/1/1963

Date Purchased Where Purchased Accessories Original Owner

TIP DOWN SCOPE BASE N

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Date Cash Date
Settlement APV APV

Per Ilion - Quote to repair under BLM

Repair/Replacement Cost Repair/Replacement Date

30.40

8/30/11: Mailing ARS, letter, form. df 9/22/11: Per Ilion - Could not duplicate concern. TA dirty. Replace TA, clean & test fire under BLM - quote. df 9/23/11: Customer called into Consumer Service Dept - apprvd quote & pd by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		9/16/2011
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
,	Description		22" 3006 SPRG
	Date Code		OK
	Bore Plugged	False	·
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	DIRTY

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6522&Type=Case

9/23/2011

. ·	11	9 .	1
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
DOIL .	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
n - :	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
<u> </u>	Sub-Assembly	Non-ISS	
	Lift	Select	.004
Sear	Notch	Slightly Worn; Functioning	O/S DOUBLE
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY
Trigger	Pull	Select	5.5#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TIP DOWN SCOPE BASE

COPY .004

6522

August 31, 2011

Bert Uytewaal 131 Rio Grande Edgewater, FL 32141 Phone: 386-409-7282

Ref: #6522, Model 700, Serial #294430

Dear Mr. Uytewaal,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and a form.

Please include a copy of this letter and form to put inside the shipping container. The letter and form inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co., LLC

Phone: 1-800-243-9700 press 0 and ask for ext 8686

Fax: 336-548-7872

NECETVE SEP 2 0 2011 BY:

294430 Model: 700

RE00240839

Could part duplicate concerne T.A. dipty. Juphon TPP, clear + Test line under BCP Rer \$ 20:00+ ship

Quode

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Print	Reset			
Model	Serial			
Number: 766 Number: 294 438				
Are you the original own				
Name: ROBERTUS CUMPAGAR	Name: ROBENIUS WHEGER Date of Purchase:			
Address (no	PO Boxes):	:		
131 KO 6 RANIE				
City: Edgenenter	State: Fla	Zip: 32 (4)		
Phone (Daytime): 386-409-7282	Fax:			
E-mail Address:(if e-mail address is provide be sent)	ed, notification of recei	pt and shipment will		
E-mail A				
I would like to receive future e				
Please describe your proble		20		
When I bought the Rifle want				
to Sloot et and pret Brellet in the				
Chamba it went of fre Metrous				
by it self - Hove int short it sevel				
500 characters left				
Ammunition Information:				
Manufacturer: Connection	Type: 30-80)		
Other (i.e. bullet weight/type, shot size,				
powder): Lord -loft				
Handload Information:				
Powder Used: 130 GRAIN	Powder Weight:			
Case/Hull Used:	Primer Used:			
Bullet Type/Shot Size: Fungton 36/36	Reloader Used:			
Firearms Care (Cleaning and Lubrication):				

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds) Nover Cleaned- Just bought
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		8/31/2011	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PKG:	10 lbs
PIEASE CHECKONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref# 6522 rifle			

LABEL INFORMATION

MAIL LABEL TO: Bert Uytewaal

131 Rio Grande

Edgewater, FL 32141 Phone: 386-409-7282

RETURN ITEM TC Remington Arms

Attn: Product Service

Ilion, NY

PUBASE COMPLETE ALL PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION





