## Remington Arms Co., Inc. Product Service Legal Case #:6421

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 236844 7/29/2011 8/4/2011 8/4/2011

**Customer Information** 

Last Name Street City Age Contact Type Business First Name State Zip 1187 E. County Line Rd. W 601-572-3660 Jackson Academy MS 329211 Reporter Academy

Incident Information

Codes Repair Est. **Medical Status** Claims **Medical Treatment** 

Unknown

PI

PD Cause:4038 Could Not Duplicate Concern

S Concern:1008 Fired on Bolt Closing

C FBC

Dealer sent gun in for consumer. Dealer stated that gun fires when bolt is closed. df

Firearm Information

Model/Ga. SKU Bbl. DOM Mfg. Type Serial CF/BA 700/270 WIN 27121 G7045857 AF 3/3/2011 8:13:55 AM Remington

Where Purchased **Date Purchased** Accessories **Original Owner** 

U

**ACADEMY SPORTS & OUTDOORS** 

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Date Cash Date Cash Settlement Release of Claims Release Date Reimbursement Settlement

Per Ilion - Check over competely - warranty

Repair/Replacement Repair/Replacement

Date Cost \$27 8/16/2011

8/16/11: Per Ilion - Could not duplicate concern. TA functions as designed. Will check over completely, clean & test fire @ n/c - warranty. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/4/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 270 WIN
	Date Code		AF
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Like new; Functioning	
	Firing Pin	Like new; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6421&Type=Case

8/16/2011

h .		1	
Bolt	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
	Condition	Like new; Functioning	
Extractor	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Like new; Functioning	
Overall	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
D	Condition	Like new; Functioning	
Receiver	Bulged	False	
Safety	Description		XMP SAFETY \
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.010
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	1 ests	False	·
Trigger	Condition	Like new; Functioning	
	Puli	Select	4#
	Altered	False	
	Sub-Assembly	X-Mark Pro	·

n a	Customer Firearm Repair - Info for Manufacturer/Repair Cente		
	$\rho Y^{(t)}$		
Today's Date	7/21/2011		
npleted By	الول Wesley Conn		
	1010		
Vanufacturer/Repair Center Information:			
Vanufacturer/Repair Center	Remington Arms Corporation Inc.		
∖ddress	Attn: Arms Service Division/Repairs 14 Hoefler Ave.		
	llion, NY 13357		
Phone Number  Nebsite	1-800-243-9700 - www.remington.com		
veusite	www.temmigton.com		
lotes			
Serial Number	G7045857		
/lodel	700 Adl		
ype of Firearm	Rifle		
Caliber/Gauge	270		
The state of the s	456 <b>39182</b>		
	AND		

Reason for Repair

RA # (if applicable)

**Return Address** 

Please return the firearm to the following address once the repair is complete:

Academy Sports + Outdoors

Attention: MOD

1187 E. County Line Rd, Jackson, Ms 39211

**Store Phone Number** 

G7045857

could not diplicate concern. T.A. Functions as designed.

Will check over completely

TeleAN+ Test Rim AT N/C WARRA Hty





