Remington Arms Co., Inc. Product Service Legal Case #:6763

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 245115 10/28/2011 10/31/2011 10/31/2011

Customer Information

TypeBusinessFirst Name Last NameStreetCityStateZipAgeContactReporter Gander MtGander Mt1912 Skibo RdFayettevilleNC28303W 910-487-4036

Incident Wallace

Wallace Brown 620 Cunningham Hollow Way Jacksonville FL 32259

H 904-504-0069

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PI

PD Cause:4038 Could Not Duplicate Concern
S Fired while safety Concern:1028 Fired With Safe ON

Unknown

Or C

11/4/11 Per note with rifle, the customer was unloading his gun and as he was doing so the gun fired while on safety. The customer only shot the gun 4 times.cm

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM

Remington CF/BA 700/243 WIN 27093 G6979486 CE 7/2/2010 1:02:41 PM

Date Purchased Where Purchased Accessories Original Owner

GANDER WAREHOUSE #1/Leban SLING U

CONCERN:FOS

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Reimbursement Release Date Reimbursement Cash Settlement Date APV

To restore confidence in rifle will replace TPA, clean and test fire at no charge

Repair/Replacement Repair/Replacement

Cost Date

47.40 11/4/2011

11/4/11 Per Ilion, could not duplicate concern. Trigger pull light. To restore confidence in rifle will replace TPA, clean and test fire at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		10/31/2011
	Product Type		RF

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6763&Type=Case

11/4/2011

	Action Type		A
	Assigned To		T/NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		24" 243 WIN
	Date Code		CE
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
,	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	Ę
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	N/A
Sear	Notch	Like new; Functioning	
	Tasta	Test Fired	False
Feeding Test	Tests	False	
	Condition	Like new; Functioning	
Tuicaan	Pull	Select	2.5#
Trigger	Altered	True	SEALANT MISSING
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		SLING



10763

Service Request Service Order # 4212



SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00727 14 Hoefler Ave

Ilion, NY 13357 Attn: REPAIR

Date Shipped: 10/25/2011

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 1-56-000-00-00-03488

Attn: Gun Parts Dept. 1912 Skibo Road

Fayetteville, NC 28303

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

700

Type: Rifle Serial Number: G6979486

Model:

Cal/Ga.: .243cal

Cased?:

DESCRIPTION OF ITEM RETURNED:

REM 700 243 CAL.SER.# G6979486 W/ SCOPE PACKAGE

REASON FOR RETURN:

CUSTOMER SAYS FIRED ON SAFE PLEASE EVALUATE & REPAIR.

ATTENTION VENDOR

Please contact me with any questions or concerns.

Walter Jackson/Randal Stroud (910) 487-4036

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

Gander Mountain

Attn: Roy Christensen

6801 120th Ave

Kenosha, WI 53142

SHIPPED NOV - PAID

1

could not suplicute concern.
Try. pull lite. To justone confidence
In juste will jup haut PA, clean + tes fine at MK

warpa why

²66979486

Model:

Gunsmith SO# 2735

GM#351 - St. Augustine 550 Belz Outlet Blvd. St. Augustine, FL 32084 (904) 829-1946 Gunsmith:



Transferred Status *

CUSTOMER INFORMATION: Home #: (904) 504-0069 Day #: Name: brown, wallace Address: 620 cunningham hollow way jacksonville, FL 32259

DATES: Acquired: Apx Comp: Completed: Cust. Called: Disposed:

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Type: Rifle Serial Number: G6979486

Model:

700

Cal/Ga.: .243cal

Firearm Value:

\$0.00 Cased?:□

Description: remington 700 synethic blued with 3-9-40

remington scope

Condition: good

Service Description: the customer was unloading his gun and as he was doing so the gun fired while on safety.

Please check out and fix what is needed and the test fire to make sure it wont happen again.

The customer only shot the gun 4 times. Send to remington.

	:LABOR	
UPC	Description	Amount
	Labor Sub Total:	\$0.00

Labor Notes:

		PARTS	
UPC	Description		Amount
		Parts Sub Total:	\$0.00

Parts Notes:

* Estimate Only *

Customer must pick up their own Firearm

	TOTALS	
	Labor Sub Total:	\$0.00
+	Parts Sub Total:	\$0.00
	Total:	\$0.00
-	Deposit Amount:	\$0.00
	Amount Due:	\$0.00

* Does not include Sales Tax *

The Child Safety Lock Act of 2005 states "it is unlawful for a dealer to sell, deliver, or transfer any handgun to any person, other than another licensee, unless the transferee (buyer) is provided with a secure gun storage or safety device for that handgun." Gander Mtn. will be providing trigger locks to all transferee's (buyer's) for a nominal fee. Transferee's may also supply their own secure gun storage or safety device.











