

Remington Arms Co., Inc.
Product Service
Legal Case #:7100

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
249358	12/7/2011	12/19/2011	12/19/2011				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Gander Mt		Gander Mt	1040 Towne Square Dr	Greensburg	PA	15601		W 724-834-2400

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired on bolt closing Concern:1008 Fired on Bolt Closing			
C				

1/16/12 Per note with rifle, twice it has fired when bolt is closed.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	27094	G6991377	OE	7/28/2010 1:09:05 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	GANDER WAREHOUSE #1/Leban	SCOPE,RINGS,TWO PIECE BASE	U			

CONCEN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
To restore confidence in rifle will replace TPA, check over and test fire under warranty						

Repair/Replacement Cost	Repair/Replacement Date
62.40	1/16/2012

Per Ilion, could not duplicate concern. To restore confidence in rifle will replace TPA, check over and test fire under warranty.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		12/19/2011
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 270 WIN
	Date Code		OE
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	---Select---	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	---Select---	N/A
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Like new; Functioning	
Trigger	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	



7100

Service Request

Service Order # 4157

20"
0E7/10
4.5"

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-01996
14 Hoefler Ave

Ilion, NY 13357
Attn: repair dept

Date Shipped: 11/29/2011 Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 0-00-000-08-25-01349
Attn: Gun Parts Dept.
1040 Towne Square Drive
Greensburg, PA 15601

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.
Model: 700

Type: Rifle
Cal/Ga.: 270 Win

Serial Number: G6991377
Cased? ☐

DESCRIPTION OF ITEM RETURNED:

700 adl

REASON FOR RETURN:

rifle fires when bolt is closed happened two times

ATTENTION VENDOR

Please contact me with any questions or concerns.

Jim Woodside
(724) 834-2400

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence.

SHIP TO ABOVE ADDRESS

Forward all invoices to: Gander Mountain Company
Attn: Cindy Kilbride
180 E. Fifth Street Suite 1300
St. Paul, MN 55101

RECEIVED
DEC 20 2011


BY: _____

could not duplicate concern
to restore confidence rifle
will replace TPA, check out + test
fire.

WA RRA wky

Serial Number: G6991377

Model: 700



RE00249358

