

Remington Arms Co., Inc.  
Product Service  
Legal Case #:6511

Case Information

| Case#  | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 239266 | 8/29/2011   | 8/30/2011       | 8/30/2011   |               |         |     |          |

Customer Information

| Type     | Business          | First Name    | Last Name       | Street         | City  | State | Zip   | Age | Contact        |
|----------|-------------------|---------------|-----------------|----------------|-------|-------|-------|-----|----------------|
| Incident | Mr T's Mercantile | Raymond Flood | Mr T's Mercanti | 111 S. Main St | Darby | MT    | 59829 |     | W 406-821-3840 |

Incident Information

| Claims | Codes                                                                               | Repair Est. | Medical Treatment | Medical Status |
|--------|-------------------------------------------------------------------------------------|-------------|-------------------|----------------|
| PI     |                                                                                     |             |                   |                |
| PD     | Cause:4038 Could Not Duplicate Concern                                              |             |                   |                |
| S      | Misfired 3 times Concern:1025 Unexplained Discharge - No Mention of Safety Position |             | Unknown           |                |
| C      |                                                                                     |             |                   |                |

9/13/11 Per letter with rifle, this gun has misfired (shot without pulling the trigger) three times.cm

Firearm Information

| Mfg.           | Type                     | Model/Ga.                  | SKU            | Serial   | Bbl. | DOM                   |
|----------------|--------------------------|----------------------------|----------------|----------|------|-----------------------|
| Remington      | CF/BA                    | 700/3006 SPRG              | 85365          | S6637313 | RB   | 11/30/2007 7:55:09 AM |
| Date Purchased | Where Purchased          | Accessories                | Original Owner |          |      |                       |
|                | CABELA S INC/WAREHOUSE / | SCOPE,RINGS,TWO PIECE BASE | U              |          |      |                       |

CONCERN: FIRED THREE TIMES WITHOUT PULLING TRIG

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

| Settlement                                                               | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|--------------------------------------------------------------------------|-------------------|--------------|---------------|-----------------|----------------|---------------|
| Per Ilion, fit new TPA, clean, test fire no charge to restore confidence |                   |              |               |                 |                |               |

| Repair/Replacement Cost | Repair/Replacement Date |
|-------------------------|-------------------------|
| 47.26                   | 9/13/2011               |

9/13/11 Per Ilion, could not duplicate concern. To restore confidence in rifle, will fit new TPA, clean, test fire no charge.cm

Examination[Remington/CF/BA]

| Part        | Sub-Part     | Code                        | Comment          |
|-------------|--------------|-----------------------------|------------------|
| Examination | Examiner     |                             | B.TRAVIS         |
|             | Exam Date    |                             | 8/30/2011        |
|             | Product Type |                             | RF               |
|             | Action Type  |                             | A                |
|             | Assigned To  |                             | T.NAGLE          |
| Cause       | 4038         | Could Not Duplicate Concern |                  |
|             | Description  |                             | 24" 3006 SPRG SS |
|             | Date Code    |                             | RB               |
|             | Bore Plugged | False                       |                  |
|             |              |                             |                  |

<http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6511&Type=Case>

9/13/2011

|                          |                        |                            |                              |
|--------------------------|------------------------|----------------------------|------------------------------|
| Barrel                   | Bulged                 | False                      |                              |
|                          | Fired                  | False                      |                              |
|                          | Fired while Obstructed |                            |                              |
|                          | Muzzle/Crown Condition | Slightly Worn; Functioning |                              |
| Bolt                     | Firing Pin             | Slightly Worn; Functioning |                              |
|                          | Shroud                 | Slightly Worn; Functioning |                              |
|                          | Face                   | Slightly Worn; Functioning |                              |
|                          | Handle                 | Slightly Worn; Functioning |                              |
|                          | Stop                   | Slightly Worn; Functioning |                              |
| Extractor                | Condition              | Slightly Worn; Functioning |                              |
|                          | Cut Condition          | Slightly Worn; Functioning |                              |
|                          | Ext/Eject Test         | False                      |                              |
| Locking                  | Block Condition        | ---Select---               |                              |
|                          | Lug Condition          | Slightly Worn; Functioning |                              |
|                          | Notch Condition        | ---Select---               |                              |
| Overall                  | Exterior Condition     | Slightly Worn; Functioning |                              |
|                          | Stock Condition        | Slightly Worn; Functioning |                              |
|                          | Fore End Condition     | ---Select---               |                              |
| Receiver                 | Condition              | Slightly Worn; Functioning |                              |
|                          | Bulged                 | False                      |                              |
| Safety                   | Description            |                            | XMP SAFETY                   |
|                          | Function               | Like new; Functioning      |                              |
|                          | Sub-Assembly           | Non-ISS                    |                              |
| Sear                     | Lift                   | ---Select---               | N/A                          |
|                          | Notch                  | Slightly Worn; Functioning |                              |
|                          | Tests                  | Test Fired                 | False                        |
| Feeding Test             |                        | False                      |                              |
| Trigger                  | Condition              | Slightly Worn; Functioning |                              |
|                          | Pull                   | ---Select---               | 4.5#                         |
|                          | Altered                | False                      |                              |
|                          | Sub-Assembly           | X-Mark Pro                 |                              |
| Non-Remington Components | Description            |                            | SCOPE, RINGS, TWO PIECE BASE |



6511

24"  
RB 11/05  
45#

August 24, 2011

(406) 821 3840  
111 S. Main St. Darby, MT 59829

DARBY · MONTANA

Ilion Firearms Plant Custom Shop  
14 Hoefler Avenue  
Ilion, New York 13357

Re: Remington Model 700  
Serial # S6637313  
30-06  
With Scope

Gentlemen:

The above gun has miss fired (shot without pulling the trigger) three times. We would appreciate your correcting this problem.

Yours very truly,

MR. T'S MERCANTILE

Raymond Flood

RECEIVED  
SEP 06 2011

BY:.....

FFL#9-81-081-02-3M-00789

Serial  
Number:

S6637313


Model: 700



RE00239266

could not duplicate concern  
to restore confidence in rifle  
will fit a new TPA, CVA M+  
Test Rifle at M/C  
# 260974





INTENTIONALLY LEFT BLANK

INTENTIONALLY LEFT BLANK