Remington Arms Co., Inc.
Product Service
Legal Case #:8211

Case Information RE# Date Opened Date Opened(PS) **Date Closed** Incident Date Pre Lit Lit Obsolete 290255 11/26/2012 11/27/2012 11/27/2012 Customer Information Contact Type **Business** First Name Last Name Street City State Zip Age Incident Charles Don Mitchell 119 Morgan Ln Greenville 42345 H 270-338-0172 Incident Information Claims Codes Repair Est. Medical Treatment Medical Status ΡI PD Cause: 4038 Could Not Duplicate Concern Unknown S Fired when he pushed the safety forward Concern: 1007 Fired on Safe Release 12/11/12 Per note on SR, he pushed the safety forward and the gun went off by itself.cm Firearm Information Mfg. Type Model/Ga. SKU Serial Bbl. DOM 8/2/2007 7:47:11 S7664804 WB CF/BA 86052 Remington 7/308 WIN AM Original Date Where Purchased Accessories Purchased Owner SPORTS SOUTH TWO PIECE BASE, BOTTOM HALF U INC RINGS,BBL RING CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/7/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Reim. Settlement Date APV Date APV

Per Ilion, will replace TPA, check over and test at no charge as goodwill

Repair/Replacement
Cost
Date
51.04
Repair/Replacement
12/11/2012

51.04 12/11/20

12/11/12 Per Ilion, could not duplicate concern. To restore confidence in rifle will replace TPA, check over and test at no charge as goodwill.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		11/28/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		J/BALIO
Cause	4038	Could Not Duplicate Concern	
	Description		20" 308 WIN SS FL
	Date Code	=	WB
	Bore Plugged	False	

Ватеі	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	· ·
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		XMP SAFETY
Salety	Function	Like new; Functioning	
	Lift	Select	.010
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	1 6212	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	4.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		TWO PIECE BASE,BOTTOM HALF RINGS,BBL RING

Service Request

Remington Service PO Box 700



Madison, NC 27025-0700

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

Service Request Number

Serial Number / Description

SR00034550

S7664804

Model SEVEN RIFLE Caliber: 308

Customer: CHARLES DON MITCHELL

119 MORGAN LANE

GREENVILLE, KY 42345 US PHONE

Email:

270-338-0172

Date of Request:

11/09/2012

4.5 1010

Printed:

11/09/2012

Destination:

Arms Services 14 Hoefler Ave Ilion, NY 13357 US

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M530 - CHECK TRIGGER SAFETY BLOCK

M992 - GUN GOES OFF BY ITSELF WHEN SAFETY IS PUSHED

Service Request Section

PUSHED SAFETY FORWARD AND GUN WENT OFF BY ITSELF.

Qty Needed

Warranty

Disc Amount

THIS CUN HASNAT Boen shot But so tim

\$7664804



could not do, conann 70 restore confidence in Pikk will rep. TPA, chick Quen + JOST AT 14/C GOOD-WILL

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00 .00

Est Sales Tax: Grand Total:

\$.00



490 ♥ Whittaker Gun's

6976 West Louisville Ln. Owensboro, KY 42301 (270) 229-0140 www.whittakerguns.com



Geniton 11-9-12	- 1800 243 9700 Parts & Repair DATE_	11-2-08	
SOLD TO			
ADDRESS			

90 Day Layaway - No Refund

QUAN	DESCRIPTION	PRICE	AMOUNT
	Rominston Ymark Pro Micool	D	838 99
	SN# 57664804		
	2) NP 2) 1010 4004		
		- 1	
			

ALL Claims and Returned Goods MUST be Accompanied By This Bill

SIGNATURE_





