

Remington Arms Co., Inc.
Product Service
Legal Case #:8299

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
292050	12/8/2012	12/10/2012	12/10/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Crown Enterprises		Crown Enterpris	145 Hutton Ranch Rd	Kalispell	MT	59901		
Incident		Gary	Nelson	1030 Falcon Acres Loop	Columbia Falls	MT	59912		H 892-2165

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

12/27/12 Per note with rifle, gun fired when pushing safety from safe to fire without touching trigger.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM08 REM	27357	G6846483	LD	3/18/2009 10:27:11 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPORTSMAN & SKI HAUS		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
To restore confidence in rifle, will replace TPA, clean and test at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	50.63	12/27/2012				

12/27/12 Per Ilion, could not duplicate concern. As a gesture of goodwill, to restore confidence in rifle, will replace TPA, clean and test at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/10/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 7MM08 REM
	Date Code		LD
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	SOME BRASS WASH
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3.5#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

Customer Waiting Returns

Sportsman and Ski Haus
Mountain Mall, Hwy 93, Whitefish, MT 59937 • 145 Hutton Ranch Rd., Kalispell, MT 59901

☐ Whitefish

☒ Kalispell

Date 11/28/2012 8299

Clerk Joe Rudolph

Customer Name Gary Nelson

Address 1030 Falcon Acres Loop

City/State Columbia Falls, MT 59912

Phone # 892-2165

Vendor Remington 12/29

Vendor Style # (or Description) 700 SPS Ser.# G684483

Retail Value \$539.99 7MM-08

Defect & Location gun fired when pushing safety
from safe to fire without touching
trigger

Serial
Number:

G6846483

Model: **700**

ved



RE00292050

RECEIVED
DEC 11 2012

BY:.....

could not dup concern
ASA Good-Will Gesture to
restore confidence in rifle
will dep. TPA, clean + test.
ATN/c

260924

22"
LO2/001
3.5"
012





