

Remington Arms Co., Inc.
Product Service
Legal Case #:7822

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
276382	7/31/2012	8/1/2012	8/1/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Piestrak's Gun Shop		Piestrak's Gun	104 Alden Mt Rd	Nanticoke	PA	18634		W 570-735-3776

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				

PI

PD

S

C

Cause:4006 Altered Adjustments or Components

Concern:1008 Fired on Bolt Closing

Unknown

8/10/12 Per not with rifle, "customer related that when he closed the bolt, the round fired."cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	26189	S6615869	OB	7/9/2007 11:16:41 AM

Date Purchased	Where Purchased	Accessories	Original Owner
	JERRY S SPORT INC	TWO PIECE BASE	U

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at 1/2 normal cost						

Repair/Replacement Cost	Repair/Replacement Date
46.21	8/10/2012

8/28/12 Per Ilion, trigger assm set screws altered. Replace TPA, clean, test at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/1/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 22-250 REM FL SS
	Date Code		OB
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown	Slightly Worn; Functioning	

	Condition		
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	1.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		TWO PIECE BASE

Best 'ak's Gun Shop

104 Alden Mt. Road - Alden
Nanticoke, PA 18634

(570) 735-3776 or FAX (570) 735-1603
1-800-281-0716

22"
037/07
1.5#
010

7822

7-26-12

Sir:

Customer Related That when he closed
the Bolt, the Round fired.

Please check it out for him

Thank you very much

Ed Brill

RECEIVED
AUG 10 2012

BY:



T.A. set screws altered.
Trig. not ret. properly.
Replace TPA, clean & test
at 1/2 normal cost.

Q

Serial
Number:

S6615869

Model: 700



RE00276382

"... the right of the people
to keep and bear Arms
shall not be infringed"





