

Remington Arms Co., Inc.
Product Service
Legal Case #:7315

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
255586	1/23/2012	1/24/2012	1/24/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Scheels	---	Scheels	2400 10th St. SW	Minot	ND	58701		H 701-852-1010 F 701-852-0972

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S FBC	Concern:1008 Fired on Bolt Closing			
C				

Dealer sent gun in for consumer. Consumer stated gun fires when bolt is closed. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	25803	G6888055	WD	8/11/2009 10:11:36 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	SIMMONS GUN SPECIALTIES I	TWO PIECE BASE,RINGS	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Replace TA - goodwill gesture						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$46					

Per Ilion - Could not duplicate concern. As goodwill gesture - to restore confidence in rifle - will replace TA, check over & test fire @ n/c. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/24/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7MM REM MAG
	Date Code		WD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown		

	Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	MARS/DENTS ON BOTTOM AHEAD OF FLOOR PLATE
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	4#
	Altered	False	
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description		TWO PIECE BASE,RINGS

DAKOTA SQUARE SCHEELS

2400 10th STREET SW

MINOT, NORTH DAKOTA 58701-6996

Phone 701.852.1010

Fax 701.852.0972

Remington
14 HOEFLER AVE.
ILION, NY 13357

DATE: 1-13-12 CLAIM #: 476285

OUR ACCOUNT #: _____

PHONE: _____

CONTACT PERSON: _____

G6888055

Model: 700



RE00255586

REASON

SHORTAGE

DEFECTIVE

OVER SHIPMENT

WRONG MDSE.

OTHER

CREDIT OUR ACCOUNT

REPLACE NO CHARGE

REPAIR & RETURN N/C

REPAIR & BILL US

AIM NUMBER ON CREDIT MEMO

QUANTITY	UNIT	ITEM NUMBER	DESCRIPTION	COST
1			REMINGTON 700 7mm BOLT RIFLE	
<u>RINGS</u>			SER# 6888055	
			GUN FIRES WHEN YOU CLOSE THE BOLT ACTION	
could not duplicate concern. AS A Good-will Gesture to restore confidence in rifle will replace TPA, check over & TEST fire at N/C			CUSTOMER INFO: KALVIN LARSON 202-4TH ST, N.E., BOWBELLS, N. DAK 58221 PH- 701-509-1097	
#260924				NEGATIV
				JAN 24 201
			TOTAL CLAIMED \$	

RETURN/CLAIM PREPARED BY:

RETURN VIA:

DATE: _____

OF CARTONS:



10-68888855
Model 700
REC-0208556



