

Remington Arms Co., Inc.
Product Service
Legal Case #:7208

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
252560	1/5/2012	1/6/2012	1/6/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Jared	Smith	13106 North 105 East	Idaho Falls	ID	83401		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		Unknown
S	Fired twice while putting it on safety	Concern:1011 Improper Safety Design		
C				
1/24/12 Per note on repair, fired twice while putting it on safety.cm				

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM RUM	84407	G6853765	KD	5/5/2009 4:32:16 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	ROSS COINS		U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, check, test no charge to restore confidence						
	Repair/Replacement Cost	Repair/Replacement Date				
	50.63	1/24/2012				

1/24/12 Per Ilion, could not duplicate concern. To restore confidence in rifle, will replace TPA, check, test no charge to restore confidence.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/6/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		26" 7MM RUM XHR
	Date Code		KD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Like new; Functioning	
	Shroud	Like new; Functioning	
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
	Stop	Like new; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Like new; Functioning	
	Stock Condition	Like new; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Like new; Functioning	
	Bulged	False	
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.010
	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Like new; Functioning	
	Pull	---Select---	3#
	Altered	False	
	Sub-Assembly	X-Mark Pro	

frmREInquiry - Repair Inquiry

Repair Number: RE00252560

Serial: G6853765 Model 700 Center Fire Caliber: 7
MM REM ULTRA MAG Produced: 05/05/2009 SKU:
84407

Repairman:

Verify Repair

Status: New 12/19/2011 1:58:10 PM

ADDRESS INFORMATION

Customer

☒ Received from

Return To

☐ Received from

Name: JARED SMITH

JARED SMITH

Address 1: 13106 NORTH 105 EAST

13106 NORTH 105 EAST

Address 2: PO Box:

PO Box:

City: IDAHO FALLS

IDAHO FALLS

State: ID Zip Code: 83401 Country: US

ID Zip Code: 83401 Country: US

FFL: 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Problems Reported

Code	Desc
M123	FORWARD TO PRODUCT SE

Repair Notes

Repairman's Comments

could not duplicate concern.
To restore confidence in rifle
will replace TPA, check over, rest
fire at N/C.

CSR Comments

FIRE TWICE WHILE PUTTING IT ON SAFTY

Refresh

Close

G6853765

Model: 700



RE00252560

26"
KDS/09
3#
1010

Serial Number:



09532570029
Page 7 of 20
S92658899



