Remington Arms Co., Inc. Product Service Legal Case #:6948

Case Information

RE# **Date Opened** 255673 1/27/2012

Date Opened(PS) 11/30/2011

Date Closed 1/30/2012

Incident Date

Pre Lit Lit

Obsolete X

Customer Information

Type Business First Name Last Name

Street

State Zip Age City

Contact

Incident

Tommy Kovar

1235 Laurel Dr Clarksburg WV 26301

H 304-203-8807 E tommykovar@aol.com

Incident Information

Claims

Codes

Repair Est.

Medical Treatment Medical Status

PΙ

PD

Altered Adjustments or Cause:4006 Components

Fired on safety release

Concern: 1007 Fired on Safe Release

Unknown

11/30/11 Per call from Kovar the bolt is hard to close and open on his rifle and it recently fired when he released the safety.cm

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl.

DOM

Remington

CF/BA

770/7MM REM MA

27412

71237564 OZ

7/28/2005 4:34:13

PM

Date Purchased

Where Purchased

Accessories

Original

Owner

WAL-MART DC 6003R-REGULAR

SCOPE, RINGS, BASE

Y

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/770/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement

Cash Reim. Date Date

APV

APV

Per Ilion, offer to replace

TPA, clean and test fire at 1/2 normal cost

Repair/Replacement Repair/Replacement

Cost

Date

41.15

2/15/2012

11/30/11 Emailing ARS.cm 2/15/12 Per Ilion, trigger pull below specs and trigger is not returning properly. Offer to replace TPA, clean and test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
1	Exam Date	•	1/30/2012

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6948&Type=Case

2/15/2012

1	Product Type	i	RF
Evamination	Action Type	<u> </u> 	
Еханинанон]	A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
	Description]	24" 7MM REM MAG
	Date Code		OZ
	Bore Plugged	False	
Barrel	Bulged	False	
Dariei	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	Ī
	Handle	Slightly Worn; Functioning	7
	Stop	Slightly Worn; Functioning	· ·
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	=
	Block Condition	Select	<u> </u>
Locking	Lug Condition	Worn; Functioning	1
	Notch Condition	Select	=
	Condition	Select	=
Magazine	Box Condition	Slightly Worn; Functioning	=
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	=
	Fore End Condition	Select	=
	Condition	Slightly Worn; Functioning	=
Receiver	Bulged	False	
	Description		M/710 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN
Trigger	Pull	Select	2#
20	Altered	True	APPEARS TO BE ALTERED
	Sub-Assembly	Other Remington	

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

24 2±

Service Request Number

Serial Number / Description

SR00005308

71237564

Model 710 RIFLE

Customer:

TOMMY KOVAR 1235 LAUREL DR

CLARKSBURG, WV 26301 US

11/30/2011 Date of Request:

Printed:

11/30/2011

Destination:

Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email: tommykovar@aol.com

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

Parts And Service Details Material

Description

Qty Needed

Warranty

Disc Amount

171237564

E002556*7*3

TRAG. pull below specs. AND triq.
is not returning properly offer
to replace TPA cleans test Rine At
1/2 NORWALL LAST.

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

	Model Number: 710		. 4
-(Are you the original owner?: YES NO		
	Name: Tommy Kowst .	Date of Furchase: 2009	
	Address (no PO Boxes): 1235	Dr. Laurel Dr.	
	city: Clark Burs	State: W.V. ZIp: 24301	
	Phone (Daytime): 304-203-655		
	E-mail Address:(if e-mail address is provided, notification	n of receipt and shipment will be	
	seni) Jamhadd@aol.com	the street of th	
	E-mail Address:		
	I Modify like to tecesiae infinite e-ursit phospies mont see	^.	
	The is very hard to close, A for two year's and this is u	S T!	
	For two year's and Ha	the same lands	
	I I I I I I I I I I I I I I I I I I I	First V	desperate as for
	For two year's and this is He and my auther guns work fine	rean this has h	
÷		with same loadse	'PPZNU
	The state of the s		
	13 .		
	500 characters left		
	t characters left	Type:	
٠.	Ammunition Information:	Туре:	
÷	Ammunition Information: Manufacturer.	Туре:	
	Ammunition Information: Manufacturer.	Type:	
	Ammunition Information: Manufacturer: Other (i.e. bullet weight/type, shot size, gowder):	Туре:	
	Ammunition Information: Manufacturer: Other (i.e. bullet weight/type, shot size, gowder): Hendload Information:	Type:	

Please send your firearm back via a traceable method of shipping to the address below.

This Service Request number is only valid for this return.

Please follow these guidelines:

- Include a copy of your proof of purchase to assist in the evaluation of your repair
- Record your serial number for future reference
- Remove <u>any accessories</u> (sling, scope, scope mounts, case, etc.) unless these items are needed to assist in the evaluation.
- Properly package your <u>unloaded</u> firearm. Do not ship in your hard case (note: Original boxes are not returned with repair)
- Do not send live/loaded or spent ammunition with your firearm.
- Please package the ammunition in a secure carton or box.
- The package should be stuffed to prevent movement.
- Include service request number.
- Shipment of live ammo must be via U.P.S. only.
- Please advise your local U.P.S. mailing center of the contents so that a special Other Regulated Materials-Domestic (ORM-D) label can be applied.

Please let us know of any address change requests by email or phone. Our returns process will take approximately 2-3 weeks to complete and a confirmation email will be sent once we have shipped your firearm.

Should you have any further questions or concerns please don't hesitate to contact us via email (<u>info@remington.com</u> <<<u>mailto:info@remington.com</u>>>) or by phone at 800-243-9700, M-F 9am - 5pm, EST. We look forward to helping you resolve this issue!

Mailing Label:		
(cut here)		

Arms Services SR# SR00005308 14 Hoefler Ave Ilion, NY 13357 US

Email:

Attn: Product Service #6948



4XX596 DEC 1, 2011 ALL CURR USD TRACKING# 1Z4XX5969065641484 1 OF 1 REF 2: HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: DV 0.00 DC 0.00 AH 0.00 SVC T/P USD RS 1.00 SD 0.00 COD 0.00 DGD 0.00 TOT PUB CHG 9.54 0.00 SP 0.00 PUB+HANDLING 9.54

ARS LABEL REQUEST FORM

DATE:	11/30/2011	Service Request #	SR00005308
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS
REQUESTED BY:	mitchellcs	email address:	Christy.Mitchell@remington.com

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.remington.com

LABEL INFORMATION

MAIL LABEL TO:

TOMMY KOVAR 1235 LAUREL DR

CLARKSBURG, WV 26301 US

RETURN ITEM TO:

Email: tommykovar@aol.com Ebad address. I called hind

ILN

Arms Services

jamhadd@aol.com

Lanks!



Christy

NOV 30, 2011 ALL CURR USD ACT WT 10.0 LBS 4XX596 SVC GNDCOM 1 OF 1 TRACKING# 124XX5969067289657 REF 1:SR00005308 REF 2:

HANDLING CHARGE 0.00 SVC T/P USD RS 1.00 SD 0.00 SINGLE-PIECE PUB RATE CHRGS: 0.00 0.00 0.00 DV 0.00 DC 0.00 AH 0.00 COB DGD TOT PUB CHG 9.54 PUB+HANDLING

ATTM: Product Service #6948





