

Remington Arms Co., Inc.
Product Service
Legal Case #:7803

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
274883	7/18/2012	7/23/2012	7/23/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Ernie	Conyers	1035 Gregory Ln	Lawrenceburg	KY	40342		H 859-583-5337 E topconyers10@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI PD S C	Cause:4015 Improper Maintenance Concern:1007 Fired on Safe Release		Unknown	

8/6/12 Per note on SR, gun has fired twice when switch from safe to fire.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	27476	E6373248	PR	6/17/1997
Date Purchased	Where Purchased	Accessories	Original Owner			
	WAL-MART WAREHOUSE #3R	SCOPE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Offer to replace TPA, clean, test fire at 1/2 normal cost						
Repair/Replacement Cost	Repair/Replacement Date					

8/6/12 Per Ilion, trigger assm dirty/rusty. Can offer to replace TPA, clean, test fire at 1/2 normal cost.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		7/23/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE


Cause	4015	Improper Maintenance	
Barrel	Description		22" 270 WIN
	Date Code		PR
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,RUSTY.TRIG WORKS SLUGGISH.WILL FOLLOW DOWN
	Pull	---Select---	8#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

Non-Remington Components	Description	SCOPE BASE
-----------------------------	-------------	------------

224
P126/97
811
1012

Serial Number:

Model: 700



RE00274883

TP19, ASSM dirty/rusty
CAN offer to replace TPA,
clean test fire at 1/2
volts, 201 F.

Refresh

Close

Monday, Jul 23 2012 ILASRPR11

4:09 AM

BY: _____
Monday, Jul 23 2012

4:09 AM



