

Remington Arms Co., Inc.
Product Service
Legal Case #:8317

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
291992	12/8/2012	12/11/2012	12/11/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Erik	Davis	109 East Main St.	Newburg	PA	17240		H 717-423-6444 E erikncarrie@hotmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

SR# 33824 - CSR Notes: Gun fires when safety is pushed off. Safety Modification Program. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	n/a	A6534087	XO	12/12/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	OSCAR ROBBINS PITTSBURGH PA	TWO PIECE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

12/13/12: Per Ilion - TA dirty & sticky & set screws altered. Replace TA, clean & test under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/11/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4006	Altered Adjustments or Components	POOR MAINTENENCE
Barrel	Description		24" 22-250 REM
	Date Code		XO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown		

	Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	MAG BOX ASSM WAS MISSALIGNED WHEN REC'D
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, STICKY TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	---Select---	2#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

frmREInquiry - Repair Inquiry

Repair Number: RE00291992 Serial: A6534087 Model 700 Center Fire Caliber: 22 Repairman:
 Verify Repair 250 REM Produced: 12/12/1977 SKU: 20000 Status: New 11/5/2012 9:08:42 AM

ADDRESS INFORMATION

Customer ☒ Received from **Return To** ☐ Received from
 Name: ERIK DAVIS ERIK DAVIS
 Address 1: 109 EAST MAIN ST 109 EAST MAIN ST
 Address 2: PO Box: PO Box:
 City: NEWBURG NEWBURG
 State: PA Zip Code: 17240 Country: US PA Zip Code: 17240 Country: US

FFL: 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information
 Phone: 717 423 6444
 Fax:
 Email: erikncarrie@hotmail.com
 Comments: FSR

Received Condition
 Good
 Condition Notes:
 CSR Notes: GUN FIRES WHEN SAFETY IS PUSHED OFF. SAFETY MODIFICATION PROGRAM.


Accessories Received

Code	Desc	Qty
A007	With Stud	2
A016	Scope Base	2

T.A. dinky & sticky & set
 5 new & 11 used. for TAN
 clean & test and. OLP for
 820. + Q

Refresh Close

Serial Number: A6534087
 Model: 700



RE00291992

SHIPPED DEC 13 PAID





