

Remington Arms Co., Inc.
Product Service
Legal Case #:7214

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
255595	1/23/2012	1/4/2012	1/24/2012	12/31/2011			

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		David	Goodrich	301A Whistle Way	Milledgeville	GA	31061		C 706-373-6095 E dgoo1269@gmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				

PD Shot a hole in the side of his house Cause:4006 Altered Adjustments or Components Unknown
S Concern:1007 Fired on Safe Release
C FSR

1/4/12: Customer called in. He stated he had a FSR with gun & shot a hole in the side of his house. No injury. He did not request comp for damage to house. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A6382511	BO	1/1/1977
Date Purchased	Where Purchased	Accessories	Original Owner			
	SOUTHERN GUN MIAMI FL	TWO PIECE BASE	N			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM			Remington/700/CF/BA			
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

1/6/12: Mailing ARS & forms. Box order# 1293936. df 1/24/12: Per Ilion - Set screws altered. Replace TA, clean & test fire under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		1/24/2012
	Product Type		RF
	Action Type		A
	Assigned To		T. NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 3006 SPRG
	Date Code		BO
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Not Functioning	WILL NOT FIRE
	Pull	---Select---	N/A
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

2211
B01/77
.007

COPY

7214

January 4, 2012

David Goodrich
301A Whistle Way
Milledgeville, GA 31061
Phone: 706-373-6095

Ref: # 7214, Model 700

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination and service request. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results. I will contact you once I get the report.

I hope this action will keep you a loyal Remington customer.

Sincerely,
Dell Fulcher
Consumer Affairs Administrator
Remington Arms Co., LLC
Phone: 1-800-243-9700 press 0 and ask for ext 8686
Fax: 336-548-7872

enclosure

RECEIVED
JAN 24 2012

Serial Number:
A6382511

Model: 700



RE00255595

BY:.....

will not fire due to the set
screws being altered. Replace
TPA, clean test fire under
BCP for \$20.+

Quote

Remington Arms Company, LLC • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025
Phone 800-243-9700 • www.remington.com

PS 27793

Service Request

Remington Service
PO Box 700

Madison, NC 27025-0700



ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. **PLEASE RETAIN THIS COPY FOR YOUR RECORDS.**

Service Request Number SR00008856	Serial Number / Description Model 700 Center Fire Caliber: 3006	Date of Request: 01/06/2012 Date Printed: 01/06/2012
Customer: DAVID GOODRICH 301A WHISTLE WAY MILLEDGEVILLE, GA 31061 US	Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US	
Email:	Email:	

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section
Product Service # 7214 - FSR

Parts And Service Details								
Material	Type	Description	Qty Needed	Warranty	Price	Disc	Amount	

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total: .00
Est Sales Tax: .00

Print

Reset

Model Number: <u>700</u>		Serial Number: <u>A6382511</u>	
Are you the original owner?: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Name: <u>DAVID Goodrich</u>		Date of Purchase: <u>10/1/2011</u>	
301 A. Whistle Way Address (no PO Boxes):			
City: <u>Milledgeville</u>		State: <u>GA</u>	Zip: <u>31061</u>
Phone (Daytime): <u>706-373-6095</u>		Fax:	
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) <u>dgoo1269@gmail.com</u>			
E-mail Address: <input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem and date of occurrence: <u>I gave this gun to my 16 year old to hunt with and the gun went off while he was showing it to his grandmother. Now the trigger will not work at all. I recently purchased a new stock for the rifle and have it installed.</u>			
500 characters left			
Ammunition Information:			
Manufacturer: <u>Remington</u>		Type: <u>Cool lockt 165 gr.</u>	
Other (i.e. bullet weight/type, shot size, powder):			
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication):			

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds) <i>6 rounds to sight in then cleaned it.</i>
How often do you clean the action? (Months or Number of rounds) <i>after each time hunting</i>
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: <i>Winchester lube oil</i>
How often do you lubricate the bore? (Months or Number of rounds) <i>after clean</i>
How often do you lubricate the action? (Months or Number of rounds) <i>after clean</i>
How often do you lubricate the trigger assembly? (Months or Number of rounds) <i>after clean</i>
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? <i>this one I bought used.</i>
What were the services performed? <i>n/a</i>
Ship your INSURED firearm by either UPS or Parcel Post to:

Remington Arms Co., Inc.
Attn: Arms Service Division
14 Hoefler Avenue
Ilion, NY 13357

☐ **WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.**

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.
:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

ARS LABEL REQUEST FORM

DATE: 01/06/2012	Service Request # SR00008856
QUANTITY: 1	WEIGHT PER PACKAGE: 10 LBS
REQUESTED BY: fulcherdm	
email address: I WILL MAIL LABEL	

Business:	Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com
------------------	---

LABEL INFORMATION

MAIL LABEL TO:	DAVID GOODRICH 301A WHISTLE WAY MILLEDGEVILLE, GA 31061 US SR00008856 Email:
RETURN ITEM TO:	ILN Arms Services



4XX596 JAN 9, 2012 ACT WT 10.0 LBS #PK 1
 SVC GND COM BL WT 10.0 LBS
 TRACKING# 1Z4XX5969065675608 ALL CURRENCY USD
 REF 1:SR00008856
 REF 2:

HANDLING CHARGE 0.00	FRT: 3RD
SHIPMENT PUB RATE CHARGES:	SVC T/P USD
DV 0.00	RS 0.60
DC 0.00	ROD 0.00
AH 0.00	PUB + HANDLING 9.61
TOT PUB CHG 9.61	

ATTN: Product Service





