

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7930

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
281976	9/12/2012	9/13/2012	9/13/2012				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		John	McNeel	128 Cannonade Trail	Corbin	KY	40701		E suidenissan@yahoo.com

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S	Fired on safety release Concern:1007 Fired on Safe Release			
C				

9/24/12 Per note on SR, consumer was unloading the firearm, moved the safety from safe to fire and the gun went off.cm

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/270 WIN	n/a	B6558722	AE	3/1/1984
Date Purchased	Where Purchased	Accessories	Original Owner			
	JERRYS SPORT SHOP MONTDALE PA		U			

CONCEN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA, clean, test at no charge						
	Repair/Replacement Cost	Repair/Replacement Date				
	77.64	9/24/2012				

9/24/12 Per Ilion, could not duplicate concern without bolt assm. Trigger assm is dirty and hard off safety. Replace TPA, clean, test at no charge.cm

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/13/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		AE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Locking	Block Condition	---Select---	
	Lug Condition	---Select---	N/A
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	REC'D LESS BOLT ASSM
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Not Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY, STICKY AND VERY HARD OFF SAFETY
	Pull	---Select---	N/A
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

frmRepairMain - FGI Repairs

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System

## frmREInquiry - Repair Inquiry

Repair Number: RE00281976

Serial: B6558722 Model 700 Center Fire Caliber: 270  
WIN

Repairman:

Verify Repair

Status: New 9/7/2012 2:17:54 PM

7930

## ADDRESS INFORMATION

Customer		Received from	Return To	Received from	
Name:	JOHN MCNEEL		JOHN MCNEEL		
Address 1:	128 CANNONADE TRAIL		128 CANNONADE TRAIL		
Address 2:		PO Box:		PO Box:	
City:	CORBIN		CORBIN		
State:	KY	Zip Code:	40701	Country:	US

FFL:

01011500

Contact / Condition Problems Estimate History / Status Shipping / Billing

## Contact Information

Phone:   
 Fax:   
 Email: suicidenissan@yahoo.com  
 Comments: ars sent

**RECEIVED**  
 SEP 17 2012

BY: .....

## Received Condition

Condition: Good  
 Condition Notes: Used B.O.A. to complete repair  
 CSR Notes: consumer was unloading the firearm. Moved the safety from safe to fire and the gun went off.

## Accessories Received

Code	Desc	Qty
A027	LESS BOLT	1

could not duplicate concern without port assm.  
 T.A. is dicky, sticky & hard off safety.  
 replace TPA, clean & test AT N/C  
 #230145

Refresh

Close

Serial Number:

B6558722

Model: 700



RE00281976









