

Remington Arms Co., Inc.
Product Service
Legal Case #:7976

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
283221	9/25/2012	9/26/2012	9/26/2012				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Scott	Mulverhill	623 East Mail St.	Malone	NY	12953		H 518-483-1576 E industrial_safetysupply@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006 Altered Adjustments or Components		Unknown	
S FBC	Concern:1008 Fired on Bolt Closing			
C				

SR# 1768 - Gun fired when closing bolt. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7MM REM MA	n/a	6486465	EU	10/1/1971
Date Purchased	Where Purchased	Accessories	Original Owner			
	PARKER DIST NEW ROCHELLE NY	TWO PIECE BASE	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$30					

9/27/12: Per Ilion - TA dirty & set screws altered. Replace TA, clean & test fire under BLM - quote. Customer paid quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		9/26/2012
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 7MM REM MAG
	Date Code		EU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	AFT MKT DM TRIG GUARD
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.010
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
	Pull	---Select---	2#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

frmREnquiry - Repair Inquiry

Repair Number: **RE00283221**

Verify Repair

Serial: 6486465 Model 700 Center Fire Caliber: 7
MM REM MAG

Repairman: Charles Swanson

Status: Estimating 9/25/2012 10:33:47 AM

ADDRESS INFORMATION

Customer

Name: SCOTT MULVERHILL

Address 1: 623 EAST MAIL STREET

Address 2: PO Box 147

City: MALONE

State: NY Zip Code: 12953 Country: US

Received from

Return To

SCOTT MULVERHILL

623 EAST MAIL STREET

PO Box 147

MALONE

NY Zip Code: 12953 Country: US

Received from

01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information

Phone:

Fax:

Email: industrial_safetysupply@yahoo.com

Comments:

Received Condition

Good

Condition

Notes

CSR

Notes: gun fired will closing bolt

Accessories Received

Code	Desc	Qty
A002	Less Mag Box	1
A007	With Stud	2
A016	Scope Base	2

RECEIVED
SEP 27 2012

BY:

6486465

Model: 700



RE00283221

*TA Luby + set screws altered
replace TPA, clean up + test fire under
BIP Box & 20.00 + ship Quote*

Close

11:40 AM

Wednesday, Sep 26 2012

11:40 AM





